



report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER TDV8 VOGUE SE
Colour	Blue
Year of manufacture	2011
Top speed	130 mph
0 - 100 km/h	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	230 kW / 313 HP / 313 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	4.367 cc
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	34.5 mpg
Consumption combined	30.1 mpg
CO2 emission	253 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-09-24
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-08
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #13	2023-05-09 13:54
MOT test number	879598348771
Result	✓ Passed
Next expiry date	2024-05-08

MOT #12	2023-05-05 09:35
MOT test number	797382158871
Result	✗ Failed
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #11	2022-05-09 16:17
MOT test number	348142200521
Result	✓ Passed

MOT #10	2021-07-17 09:02
MOT test number	223077334847
Result	✓ Passed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9** 2020-06-24 14:37**MOT test number** 796369229294**Result** ✓ Passed**MOT #8** 2019-07-12 12:04**MOT test number** 223869882044**Result** ✓ Passed**Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect Light misting (5.3.2 (b))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect Light misting (5.3.2 (b))**MOT #7** 2018-07-14 10:27**MOT test number** 304196149939**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm, bush cracking/splitting (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing outer edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm, bush cracking/splitting (5.3.4 (a) (i))**MOT #6** 2017-07-19 15:29**MOT test number** 144524800079**Result** ✓ Passed**MOT #5** 2017-02-25 11:57**MOT test number** 927669171079**Result** ✓ Passed**MOT #4** 2016-02-23 12:22**MOT test number** 564355669658**Result** ✓ Passed



MOT #3	2015-02-25 10:36
MOT test number	887896555014
Result	✓ Passed

MOT #2	2015-02-24 13:53
MOT test number	258505255030
Result	✗ Failed
<div><div>Fail</div>Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div>	

MOT #1	2014-08-14 12:41
MOT test number	199876424279
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
8 May 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	8 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	EX61YSL
Plate since	2024-03-28
Current registration	EX61YSL
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-20
Last registration	2023-05-09
Complete history	See info



Registration #1	2011-09-20	17 mi
Registration #2	2014-08-14	30.267 mi
Registration #3	2015-02-24	36.945 mi
Registration #4	2015-02-25	36.945 mi
Registration #5	2016-02-23	43.923 mi
Registration #6	2017-02-25	51.745 mi
Registration #7	2017-07-19	53.494 mi
Registration #8	2018-07-14	63.967 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2020-05-20	85.277 mi
Registration #11	2021-05-20	95.277 mi
Registration #12	2022-05-20	105.277 mi
Registration #13	2023-05-20	115.277 mi
Registration #14	2024-05-20	125.277 mi
Registration #15	2025-05-20	135.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2216 mm
Height	1865 mm
Length	4967 mm
Wheel base	2880 mm
Kerb weight	2710 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0006899448DT