






report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Blue
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-12-31

Pictures 1

Listing price View report



source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-20
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	36
Total items failed	1

MOT #10		2023-07-21 10:49
MOT test r	number	492268930922
Result		✓ Passed
Next expir	ry date	2024-07-20
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #9		2022-05-23 08:57
MOT test	number	817826470780
Result		✓ Passed
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Slight movement in offside and nearside front top shock absorber mounts	
Advice	Rear brake discs worn	
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Offside and nearside rear brake pipes corroded	

CarCheck.co.uk page 3/13



Advice

HK140VV

report date: 2024-03-29

MOT #8 2022-05-20 10:46 226245032604 **MOT** test number Result **★** Failed **Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i)) Advice Offside and nearside rear brake pipes corroded Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Headlamp light source and lamp not compatible (4.1.4 (c)) **MAJOR MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f)) Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i)) Slight movement in offside and nearside front top shock absorber mounts Advice Advice Nearside Rear Nail in tyre Advice Rear brake discs worn MAJOR Offside Headlamp light source and lamp not compatible (4.1.4 (c))

MOT #7	2021-06-11 12:45
MOT test	number 777059014141
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin recommend removal of wheels for better inspection (1.1.13 (a)
Advice	Offside front tyre worn on inner edge (205/55r16)

Offside Rear Service brake binding but not excessively (1.2.1 (f))

CarCheck.co.uk page 4/13



MOT #6 2021-06-05 10:04

MOT test number 367834445431

Result X Failed

Advice Front Brake pad(s) wearing thin recommend removal of wheels for better inspection (1.1.13 (a)

(ii))

Advice Offside front tyre worn on inner edge (205/55r16)

MAJOR Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #5 2020-06-18 10:56

MOT test number 187552042024

Result Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin 90% worn (1.1.13 (a) (ii))

MOT #4 2019-06-14 15:51

MOT test number 384724547938

Result

Passed

Advice Front Brake pad(s) wearing thin approx 90% worn (1.1.13 (a) (ii))

MOT #3 2018-06-16 09:55

MOT test number 542873017647

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3-4mm 2055516 cracked in tread grooves (5.2.3 (e))

Advice Under body covers fitted not allowing full inspection

Advice Offside Front Tyre worn close to legal limit/worn on edge 3-4mm cracked in tread grooves (5.2.3

(e))

Advice Both rear tyres perished on sidewalls

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2

MOT test number

Result

Advice Both rear tyres cracking on sidewalls

Advice Offside Rear Slight brake bind

MOT #1

Result

Advice Both rear tyres cracking on sidewalls

Fail Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Offside Rear Slight brake bind

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

HK140VV

report date: 2024-03-29

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

Plate changes

See in this check if this RENAULT had different number plates.

***The company of the company of

More info >

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-06-26
Last registration	2023-07-21
Complete history	See info



Registration #1	2014-06-26	11 mi
Registration #2	2017-06-17	46.542 mi
Registration #3	2017-06-17	46.542 mi
Registration #4	2018-06-16	62.850 mi
Registration #5	2019-06-14	77.695 mi
Registration #6	2020-06-18	85.666 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.177 au

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2641 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/3

Number of axles 2

Engine number D292824