



report date: 2024-03-29

## General information

Make	VOLVO
Model	C30 D5 S
Colour	Red
Year of manufacture	2010
Top speed	140 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-12-31
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-08
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	9
Total items failed	4

MOT #16	2023-12-19 17:55
MOT test number	660496714933
Result	✓ Passed
Next expiry date	2025-01-08

MOT #15	2023-01-09 12:54
MOT test number	561893743037
Result	✓ Passed

MOT #14	2021-11-29 13:55
MOT test number	759294877488
Result	✓ Passed
Advice	Rear Inner Tyre worn close to legal limit/worn on edge Both O/Side & N/Side (5.2.3 (e))

MOT #13	2021-11-22 16:09
MOT test number	749805182590
Result	✗ Failed
Advice	Rear Inner Tyre worn close to legal limit/worn on edge Both O/Side & N/Side (5.2.3 (e))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**MOT #12** 2021-02-19 13:06**MOT test number** 730535683136**Result** ✓ Passed**MOT #11** 2019-12-02 10:04**MOT test number** 893181176365**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge all 4 inner edge (5.2.3 (e))**MOT #10** 2019-12-02 10:04**MOT test number** 893002930897**Result** ✗ Failed**Pass with rectification** Direction indicator incorrect colour o/s/f (4.4.3 (a))**Advice** Tyre worn close to legal limit/worn on edge all 4 inner edge (5.2.3 (e))**MOT #9** 2018-12-03 10:01**MOT test number** 864384367421**Result** ✓ Passed**MOT #8** 2017-12-12 13:14**MOT test number** 946615903522**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases rear box (7.1.2)

**MOT #7** 2017-12-12 13:14**MOT test number** 896525903814**Result** ✗ Failed**Pass with rectification** Front position lamp(s) not working both (1.1.A.3b)**Advice** Exhaust has a minor leak of exhaust gases rear box (7.1.2)**Pass with rectification** Headlamp aim too low both (1.8)**MOT #6** 2017-05-10 09:59**MOT test number** 528457179149**Result** ✓ Passed**MOT #5** 2016-07-26 16:18**MOT test number** 132152962698**Result** ✓ Passed**MOT #4** 2015-08-04 11:50**MOT test number** 916436015249**Result** ✓ Passed**MOT #3** 2015-03-02 17:10**MOT test number** 279361665070**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2014-02-27 10:30**MOT test number** 539718054099**Result** ✓ Passed



MOT #1	2013-02-19 12:56
MOT test number	897340253018
Result	✓ Passed
<div><div>Notice</div>Under-trays fitted obscuring some underside components</div> <div><div>Notice</div>Engine covers fitted obscuring some components in the engine bay</div>	



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-01
Last registration	2023-12-19
Complete history	<a href="#">See info</a>



Registration #1	2010-03-01	24 mi
Registration #2	2013-02-19	54.642 mi
Registration #3	2014-02-27	69.557 mi
Registration #4	2015-03-02	83.642 mi
Registration #5	2015-08-04	84.108 mi
Registration #6	2016-07-26	98.752 mi
Registration #7	2017-05-10	110.197 mi
Registration #8	2017-12-12	121.489 mi
Registration #9	2017-12-12	121.489 mi
Registration #10	2018-05-29	121.577 mi
Registration #11	2018-05-29	121.577 mi
Registration #12	2018-05-29	121.577 mi
Registration #13	2018-05-29	121.577 mi
Registration #14	2018-05-29	121.577 mi
Registration #15	2018-05-29	121.577 mi
Registration #16	2018-05-29	121.577 mi
Registration #17	2018-05-29	121.577 mi
Registration #18	2018-05-29	121.577 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1474 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	704792
---------------	--------