





report date: 2024-03-28

## General information

Make	FORD
Model	FUSION FUSION +
Colour	Black
Year of manufacture	2008
Top speed	109 mph
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	100 BHP	
Max. torque	146 Nm at 4.000 rpm	
Engine capacity	1.596 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	27.4 mpg	
Consumption extra urban	46.3 mpg	
Consumption combined	37.2 mpg	
CO2 emission	181 g/km	
CO2 label	I	



CarCheck.co.uk page 1/12




# Internet history

## Entry 1

Date 2021-12-27

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



Topole dutoi 2024

# MOT history

MOT expiry date	2025-01-02
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	8
Total items failed	4

MOT #16		2024-01-03 10:45
MOT test	number	419310193089
Result		✓ Passed
Next expi	ry date	2025-01-02
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sign	des (1.1.14 (a) (ii))
Advice	Front Brake pipe corroded, covered in grease or other material both sides (	1.1.11 (c))
Advice	Advice Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))	
Advice	Wax oil to chassis to floor front to back	
Advice	Rear Sound deadening material not fully secure (8.1.1 (b) (i))	
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))	

MOT #15	2023-01-19 15:1
MOT test	number 53387512834
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



YC58FYA

report date: 2024-03-28

MOT #14 2023-01-12 11:14

**MOT test number** 977714338151

**Result** X Failed

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))

**Fail** Central Rear Brake pipe leaking on a hydraulic braking system main front to rear pipe goes to o/s rear leaking on joint and not secure to clip (1.1.11 (b) (ii))

**MOT #13** 2022-02-07 10:55

**MOT test number** 736342681437

**Result** ✓ Passed

**MOT #12** 2022-02-04 16:08

**MOT test number** 912519640647

Result X Failed

**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #11** 2020-09-21 08:13

**MOT test number** 834503208126

**Result** ✓ Passed

**MOT #10** 2020-09-21 08:13

**MOT test number** 514394259158

**Result** ★ Failed

**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

MOT #9 2019-09-23 08:23

MOT test number 440601726464

Result 

Passed

CarCheck.co.uk page 4/12



MOT #8	2018-09-10 08:29
MOT test number	872305287208
Result	✓ Passed
MOT #7	2017-09-12 09:33
MOT test number	169734465577
Result	✓ Passed
MOT #6	2016-09-12 08:13
MOT test number	985340615753
Result	✓ Passed
MOT #5	2015-09-08 00:00
MOT test number	690500183798
Result	<b>✓</b> Passed
MOT #4	2014-09-22 15:59
MOT test number	368085764230
Result	
Result	✓ Passed
MOT #3	2013-09-20 09:29
MOT test number	276403063210
Result	✓ Passed
MOT #2	2012-09-21 09:37
MOT test number	348625362209
Result	✓ Passed
MOT #1	2011-09-23 14:00
MOT test number	859656261226
Result	✓ Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	2 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when misterly		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ve?
***************************************		
***************************************		
***************************************		
	More info	<b>&gt;</b>
Plate changes  See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-11-18
Last registration	2024-01-03
Complete history	See info



Registration #1	2008-11-18	24 mi
Registration #2	2011-09-23	6.613 mi
Registration #3	2012-09-21	10.708 mi
Registration #4	2013-09-20	15.677 mi
Registration #5	2014-09-22	22.423 mi
Registration #6	2015-09-08	31.175 mi
Registration #7	2016-09-12	37.390 mi
Registration #8	2017-09-12	47.973 mi
Registration #9	2018-09-10	55.766 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 8Y86107