





report date: 2024-03-29

### General information

| Make                | FORD                 |
|---------------------|----------------------|
| Model               | FUSION ZETEC CLIMATE |
| Colour              | Red                  |
| Year of manufacture | 2008                 |
| Top speed           | 101 mph              |
| Gearbox             | 5 speed Manual       |

# Engine & fuel consumption

| Power                   | 78 BHP              |
|-------------------------|---------------------|
| Max. torque             | 124 Nm at 3.500 rpm |
| Engine capacity         | 1.388 сс            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 33.2 mpg            |
| Consumption extra urban | 53.3 mpg            |
| Consumption combined    | 43.5 mpg            |
| CO2 emission            | 154 g/km            |
| CO2 label               | G                   |



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-08-07

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

# MOT history

| MOT expiry date    | 2024-11-06 |
|--------------------|------------|
| MOT pass rate      | 76 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 4          |
| Total advice items | 23         |
| Total items failed | 1          |

| MOT #17   |   | 2023-11-06 10:52 |
|-----------|---|------------------|
| MOT test  | number  | 755712114360     |
| Result    |   | ✓ Passed         |
| Next expi | y date  | 2024-11-06       |
| Advice    | Items removed from driver's view prior to test                              |                  |
| Advice    | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #16  | 2022-11-04 14:45   |
|--|--|
| MOT test   | number 605817424199  |
| Result   | ✓ Passed   |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing PERISHED (5.2.3 (d) (ii))          |  |
| Advice Brake pipe corroded, covered in grease or other material OFFSIDE FRONT TO REAR (1.1.11 (c)) |  |
| Advice   | Nearside Front Tyre slightly damaged/cracking or perishing PERISHED (5.2.3 (d) (ii)) |

CarCheck.co.uk page 3/13



MOT #15 2022-11-03 15:53

MOT test number 437190347701

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing PERISHED (5.2.3 (d) (ii))

Advice Brake pipe corroded, covered in grease or other material OFFSIDE FRONT TO REAR (1.1.11 (c))

Advice Nearside Front Tyre slightly damaged/cracking or perishing PERISHED (5.2.3 (d) (ii))

Advice Offside Hydraulic leak, but not excessive DRIVESHAFT OIL SEAL (8.4.1 (a) (i))

MAJOR Brakes imbalanced across an axle OFFSIDE FRONT WEAK COMPARED TO NEARSIDE ( 49% ) (1.2.1

(b) (i))

**MOT #14** 2021-10-13 11:12

**MOT test number** 991139322643

Result \( \sqrt{Passed} \)

**MOT #13** 2021-10-13 08:17

**MOT test number** 552604549820

Result X Failed

**MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))

**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #12 2020-11-02 10:40

**MOT test number** 325234543074

**Result** 
✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

| MOT #11  |  | 2019-11-07 14:11 |
|----------|--|------------------|
| MOT test | number   | 338514078155     |
| Result   |  | ✓ Passed         |
| Advice   | Corrosion to suspension and braking components |                  |
| Advice   | Items removed from driver's view prior to test |                  |

| MOT #10  |  | 2019-11-07 09:53 |
|----------|--|------------------|
| MOT test | number   | 221190802515     |
| Result   |  | <b>X</b> Failed  |
| MAJOR    | Rear Exhaust has a major leak of exhaust gases (6.1.2 (a)) |                  |
| Advice   | Corrosion to suspension and braking components             |                  |
| Advice   | Items removed from driver's view prior to test             |                  |

| MOT #9                          | 2018-11-05 10:45 |
|---------------------------------|------------------|
| MOT test number                 | 881385170676     |
| Result                          | <b>✓</b> Passed  |
|                                 |                  |
| MOT #8                          | 2017-10-12 10:29 |
| MOT test number                 | 678570955758     |
| Result                          | <b>✓</b> Passed  |
|                                 |                  |
| MOT #7                          | 2016-10-28 09:14 |
| MOT test number                 | 601939208107     |
| Result                          | <b>✓</b> Passed  |
| Advice Top stop lamp Inop       |                  |
| Advice Rear heatshield insecure |                  |
|                                 |                  |

CarCheck.co.uk page 5/13



Pass with rectification

YC58PKE

report date: 2024-03-29

| MOT #6                       | 2015-10-27 16:09 |
|------------------------------|------------------|
| MOT test number              | 626865964086     |
| Result                       | <b>✓</b> Passed  |
| Advice Center Stop Lamp Inop |                  |

| MOT #5   | 2014-11-01 11:09 |
|--|------------------|
| MOT test number  | 669405604312     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #4   | 2013-11-06 14:09 |
| MOT test number  | 218610413334     |
| Result   | ✓ Passed         |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) |                  |

| MOT #3          | 2012-11-02 15:12 |
|-----------------|------------------|
| MOT test number | 295017402323     |
| Result          | <b>✓</b> Passed  |
| Notice Oil leak |                  |

| MOT #2          | 2011-09-13 12:00 |
|-----------------|------------------|
| MOT test number | 339326451459     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2011-09-13 12:00 |
| MOT test number | 559306051251     |
| Result          | <b>X</b> Failed  |

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 6/13



report date: 2024-03-29

### Tax & MOT check



| Tax status       | Valid until 1 August |
|------------------|----------------------|
| Days left        | 93                   |
| MOT expiry date  | 6 November 2024      |
| Full MOT history | See MOT history      |

### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

YC58PKE

report date: 2024-03-29

# For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this FORD had different number plates.

More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 11/13



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 18         |
| First mileage registration | 2008-10-24 |
| Last registration          | 2023-11-06 |
| Complete history           | See info   |



| Registration #1  | 2008-10-24 | 14 mi     |
|------------------|------------|-----------|
| Registration #2  | 2011-09-13 | 24.922 mi |
| Registration #3  | 2012-11-02 | 28.285 mi |
| Registration #4  | 2013-11-06 | 31.139 mi |
| Registration #5  | 2014-11-01 | 35.532 mi |
| Registration #6  | 2015-10-27 | 40.195 mi |
| Registration #7  | 2016-10-28 | 44.923 mi |
| Registration #8  | 2017-10-12 | 49.265 mi |
| Registration #9  | 2018-11-05 | 53.178 mi |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 11.777 es |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 11.777 es |
| Registration #16 |            | 11.777 es |
| Registration #17 |            | 11.777 es |
| Registration #18 |            | 11.177 es |

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 |                 |
| 60482 |                 |
| 60501 |                 |
| 0566  |                 |
| 60567 |                 |
| 60569 |                 |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1963 mm |
|---------------------|---------|
| Height              | 1543 mm |
| Length              | 4013 mm |
| Wheel base          | 2485 mm |
| Kerb weight         | 1161 kg |
| Max. allowed weight | 1605 kg |

# Additional information

| Fuel tank capacity                | 45 I                  |           |
|-----------------------------------|-----------------------|-----------|
| Fuel delivery                     | Multi-Point Injection |           |
| Number of doors                   | 5                     |           |
| Number of seats<br>CarCheck.co.uk | 5 pa                  | age 13/13 |

Number of axles2Engine number8C32389