





report date: 2024-03-28

### General information

Make	CITROEN
Model	C1 PURETECH FEEL
Colour	White
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	82 BHP	
Max. torque	116 Nm at 2.750 rpm	
Engine capacity	1.200 cc	
Cylinders	3	
Fuel type	Petrol	
Consumption city	52.3 mpg	
Consumption extra urban	76.3 mpg	
Consumption combined	65.7 mpg	
CO2 emission	99 g/km	
CO2 label	A	



CarCheck.co.uk page 1/11



## Internet history

#### Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-31
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	10
Total items failed	3

MOT #9		2023-11-01 09:25
MOT test	number	680136538017
Result		✓ Passed
Next expi	ry date	2024-10-31
Advice	Nearside Front Tyre worn close to legal limit/worn on edge tyre on 1.6mm	m (5.2.3 (e))
<b>Advice</b> (6.1.2 (a))	Offside Rear Exhaust mounting defective silencer hanger rusted off but s	silencer secured with wire
Advice	Offside Front Tyre worn close to legal limit/worn on edge tyre on 1.8mm	(5.2.3 (e))

MOT #8	2023-11-01 09:25	
MOT test number	530333967708	
Result	<b>X</b> Failed	
Advice Nearside Front Tyre worn close to legal limit/worn on edge tyre on 1.6mm (5.2.3 (e))  Advice Offside Rear Exhaust mounting defective silencer hanger rusted off but silencer secured with wire		
(6.1.2 (a))		
Pass with rectification Near	side Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Offside Front Tyre wor	n close to legal limit/worn on edge tyre on 1.8mm (5.2.3 (e))	

MOT #7	2022-12-14 11:23
MOT test number	885758098776
Result	✓ Passed
Advice Front Exhaust mounting defective rubber broken and wired up (6.1.2 (a))	

CarCheck.co.uk page 3/11



MOT #6 2022-12-14 11:23

**MOT test number** 911007424747

Result × Failed

Advice Front Exhaust mounting defective rubber broken and wired up (6.1.2 (a))

**Pass with rectification** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**MOT #5** 2021-11-10 09:36

**MOT test number** 324854428468

**Result** ✓ Passed

MOT #4 2021-11-09 09:51

**MOT test number** 732166230341

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-11-12 15:39

**MOT test number** 779471165867

**Result** ✓ Passed

**MOT #2** 2020-03-08 12:59

**MOT test number** 323275293011

Result \( \sqrt{Passed} \)

**Advice** Front Exhaust mounting defective (6.1.2 (a))

MOT #1 2019-03-08 15:28

**MOT test number** 243365891742

Result 

Passed

CarCheck.co.uk page 4/11



#### Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	31 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		EN
**************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	OK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-03
Last registration	2023-11-01
Complete history	See info



Registration #1	2016-03-03	28 mi
Registration #2	2019-03-08	29.184 mi
Registration #3	2020-03-08	41.748 mi
Registration #4	2020-11-12	46.286 mi
Registration #5		11.777 es
Registration #6	2021-11-09	53.409 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		70.777 es

More info >

CarCheck.co.uk page 10/11



# Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



# Dimensions & weight

Width	1884 mm
Height	1460 mm
Length	3466 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1240 kg

# Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	B2220021026

CarCheck.co.uk page 11/11