





report date: 2024-03-28

### General information

Make	MINI
Model	ROADSTER COOPER SD
Colour	Red
Year of manufacture	2013
Top speed	130 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	141 BHP	
Max. torque	305 Nm at 1.750 rpm	
Engine capacity	1.995 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	53.3 mpg	
Consumption extra urban	70.6 mpg	
Consumption combined	62.8 mpg	
CO2 emission	118 g/km	
CO2 label	С	



CarCheck.co.uk page 1/12



# Internet history

### Entry 1

Date 2021-08-27

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-24
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	13
Total items failed	1

MOT #14	2024-04-25 08:49
MOT test number	651896197837
Result	✓ Passed
Next expiry date	2025-04-24

MOT #13	2024-04-22	10:44
MOT test	<b>number</b> 35727707	9216
Result	×	Failed
MAJOR	Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
MAJOR	MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
MAJOR	Nearside Front Brake insecure wear lead indicator (1.1.21 (c))	

MOT #12		2023-02-27 17:46
MOT test	number	141008593081
Result		✓ Passed
MOT #11		2023-02-25 12:45
MOT test	number	844496196201
Result		<b>X</b> Failed
MAJOR	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10	2022-01-28 20:50
MOT test number	887577381589
Result	✓ Passed
MOT #9	2021-01-12 10:14
MOT test number	536848714080
Result	✓ Passed
MOT #8	2020-01-20 12:34
MOT test number	925768958452
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7		2020-01-20 10:01
MOT test	number	182523160860
Result		<b>X</b> Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6	2019-01-10 09:33
MOT test number	601816460040
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2019-01-10 09:17

MOT test number 718360129306

**Result** X Failed

MAJOR Rear Registration plate does not conform to the specified requirements (0.1 (d))

**MAJOR** Front Registration plate does not conform to the specified requirements (0.1 (d))

MOT #4 2018-01-24 11:25

**MOT test number** 624773959255

**Result** 
✓ Passed

MOT #3 2017-12-28 16:41

**MOT test number** 390665971390

Result \rightarrow Passed

MOT #2 2016-12-16 10:25

**MOT test number** 313122479648

**Result** 
✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1 2016-12-16 10:25

**MOT test number** 775208730478

**Result** X Failed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Pass with rectification** Offside Headlamp aim too high (1.8)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	24 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

$\sim$		100	
Owi	ner	nıs	torv

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>have the current and the full report have the current and the full report have the current and the full report have the current and the full report <u>have the current and the full report have the current and previous owner(s) have this MINI? How many owners did not the full report the current and previous owner(s) have the full report and the current and previous owner(s) have the full report and the full report and the full report and the current and previous owner(s) have the full report and the full re</u></u>		e?
***************************************		
manage of the same		
************		
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK C	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-12-28
Last registration	2024-04-25
Complete history	See info



Registration #1	2013-12-28	7 mi
Registration #2	2016-12-16	58.352 mi
Registration #3	2016-12-16	58.352 mi
Registration #4	2017-12-28	72.110 mi
Registration #5	2018-01-24	72.110 mi
Registration #6	2019-01-10	84.827 mi
Registration #7	2019-01-10	84.827 mi
Registration #8	2020-01-20	95.646 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 ms

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



report date: 2024-03-28

### Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3729 mm
Wheel base	2467 mm
Kerb weight	1250 kg
Max. allowed weight	1680 kg

# Additional information

Fuel tank capacity	40 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4 page	12/12

Number of axles 2

**Engine number** 71528575