





report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Black
Year of manufacture	2010
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.5 mpg
CO2 emission	196 g/km
CO2 label	J



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2021-11-05

Pictures 27

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-11-03

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2023-03-28
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #12	2022-03-29 08:43
MOT test number	917820594089
Result	✓ Passed
Next expiry date	2023-03-28

MOT #11	2021-05-11 09:51
MOT test number	313280178380
Result	✓ Passed

MOT #10	2021-05-05 09:51
MOT test number	168969999718
Result	X Failed
Fail Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #9	2	020-04-22 08:22
MOT test	number	276749490628
Result		✓ Passed
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2020-04-15 08:31 862258190276 **MOT** test number Result × Failed **Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i)) Fail Central Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Advice Offside Front Nail in tyre

MOT test number

Result

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #6	2018-05-09 11:21
MOT test number	865542122243
Result	✓ Passed

MOT #5		2017-03-15 13:31
MOT test	number	986203140595
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4	2016-02-01 15:01
MOT test number	543247536379
Result	✓ Passed
MOT #3	2015-02-09 12:27
MOT test number	199690845403
Result	✓ Passed
MOT #2	2014-09-23 10:11
MOT test number	605856464237
Result	✓ Passed
MOT #1	2013-09-17 09:04
MOT test number	965470863235
Result	✓ Passed
Notice Offside front tyre has sidewall damage	

CarCheck.co.uk page 5/12



YS10KRF report date: 2024-03-29

Tax & MOT check



X MOT

Tax expired: 1 June 2022

Expired: 28 March 2023

Tax status	Expired at 1 June 2022
Days left	697 days too late
MOT expiry date	28 March 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12




report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



YS10KRF report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downlo	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK NA
Plate since	
Current registration	IK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



YS10KRF report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-08-05
Last registration	2022-03-29
Complete history	See info



Registration #1	2010-08-05	11 mi
Registration #2	2013-09-17	25.845 mi
Registration #3	2014-09-23	30.868 mi
Registration #4	2015-02-09	32.269 mi
Registration #5	2016-02-01	36.087 mi
Registration #6	2017-03-15	39.097 mi
Registration #7	2018-05-09	41.863 mi
Registration #8	2019-05-01	48.065 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		

More info >

CarCheck.co.uk page 11/12



YS10KRF report date: 2024-03-29

			_		
- 11	manc	Innc	λ.	MOL	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1415 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431331085

CarCheck.co.uk page 12/12