



report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SZ3
Colour	White
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	93 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C





MOT history

MOT expiry date	2025-02-10
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	26
Total items failed	4

MOT #11	2024-02-11 13:23
MOT test number	430491481453
Result	✓ Passed
Next expiry date	2025-02-10

MOT #10	2023-01-16 12:32
MOT test number	392402821654
Result	✓ Passed

- Advice** Nearside Rear Fuel Pipe/s corroded front of tank
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to flex (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to backplate (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to flex (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to backplate (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9**

2021-12-24 12:57

MOT test number

844964771963

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to flex and to back plate (1.1.11 (c))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to flex and to back plate (1.1.11 (c))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8

2021-12-14 16:29

MOT test number

965970206143

Result

✗ Failed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to flex and to back plate (1.1.11 (c))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Headlamp levelling device inoperative (4.1.5 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to flex and to back plate (1.1.11 (c))

MOT #7

2020-11-27 12:57

MOT test number

324817561539

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2020-11-27 12:57**MOT test number** 194429899023**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #5** 2019-06-10 15:24**MOT test number** 917350359600**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2018-07-28 07:40**MOT test number** 114926113349**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn to 3mm 185/55/16 (5.2.3 (e))**MOT #3** 2017-07-29 08:58**MOT test number** 751525424388**Result** ✓ Passed**MOT #2** 2016-07-05 13:52**MOT test number** 919413723713**Result** ✓ Passed**MOT #1** 2015-07-14 17:28**MOT test number** 658865795131**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
10 February 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	10 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	DF12XKB
Plate since	2019-09-29
Current registration	DF12XKB
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-07-31
Last registration	2024-02-11
Complete history	See info



Registration #1	2012-07-31	13 mi
Registration #2	2015-07-14	33.486 mi
Registration #3	2016-07-05	40.838 mi
Registration #4	2017-07-29	43.132 mi
Registration #5	2018-07-28	45.827 mi
Registration #6	2019-06-10	47.517 mi
Registration #7	2020-05-20	50.277 mi
Registration #8	2021-05-20	53.277 mi
Registration #9	2022-05-20	56.277 mi
Registration #10	2023-05-20	59.277 mi
Registration #11	2024-02-11	62.277 mi
Registration #12	2024-02-11	62.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1050 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	K12B-1407482