



report date: 2024-03-28

General information

Make	VOLVO
Model	C70 SE
Colour	Silver
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	229 Nm at 4.400 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.9 mpg
Consumption extra urban	42.2 mpg
Consumption combined	31.4 mpg
CO2 emission	215 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-18
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-07
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	39
Total items failed	25

MOT #22	2023-12-08 12:29
MOT test number	131529606342
Result	✓ Passed
Next expiry date	2024-12-07
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #21	2023-12-07 17:43
MOT test number	374292084205
Result	✗ Failed
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #20	2022-10-04 16:54
MOT test number	470514660856
Result	✓ Passed
Advice	Nearside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19	2021-10-27 16:30
MOT test number	645805606329
Result	✓ Passed

**MOT #18** 2021-10-15 13:43**MOT test number** 768638142229**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #17** 2021-03-04 12:28**MOT test number** 735266837269**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all four (1.1.14 (a) (ii))**Advice** Service brake fluctuating, but not excessively all four (1.2.1 (e))**MOT #16** 2021-03-04 10:05**MOT test number** 825983103441**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened all four (1.1.14 (a) (ii))**Fail** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Service brake fluctuating, but not excessively all four (1.2.1 (e))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #15**

2019-09-17 10:11

MOT test number

429461813653

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front marker light out

Minor Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #14

2019-09-16 08:29

MOT test number

367339812725

Result

✗ Failed

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Nearside Front marker light out

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Minor Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #13**

2019-06-07 09:21

MOT test number

407732378669

Result

✗ Failed

- Fail** Nearside Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #12

2018-04-23 14:07

MOT test number

287792836927

Result

✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front side marker light out

**MOT #11**

2018-04-23 12:22

MOT test number

900943977695

Result

✗ Failed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice No oil on dipstick (topped up 4 ltrs)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Advice Nearside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front side marker light out

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Side repeater not working (1.4.A.2c)

MOT #10

2017-04-08 12:34

MOT test number

245143095177

Result

✓ Passed

MOT #9

2016-04-08 10:31

MOT test number

862244658607

Result

✓ Passed

Advice All four tyres wearing on inside edges.

**MOT #8** 2015-04-14 09:59**MOT test number** 189974505192**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-04-14 09:59**MOT test number** 415254705126**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-04-11 11:09**MOT test number** 825171904142**Result** ✓ Passed**Notice** Coolant leak,radiator appears to be damp**MOT #5** 2013-04-24 11:19**MOT test number** 856354513176**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-03-06 16:53**MOT test number** 228236462005**Result** ✓ Passed**MOT #3** 2011-03-07 16:32**MOT test number** 346936761063**Result** ✓ Passed



MOT #2	2011-03-04 17:07
MOT test number	116413961468
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2010-04-01 10:39
MOT test number	484221190098
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
7 December 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	7 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-03-28
Last registration	2023-12-08
Complete history	See info



Registration #1	2007-03-28	27 mi
Registration #2	2010-04-01	15.914 mi
Registration #3	2011-03-04	17.323 mi
Registration #4	2011-03-07	17.329 mi
Registration #5	2012-03-06	28.851 mi
Registration #6	2013-04-24	31.206 mi
Registration #7	2014-04-11	38.155 mi
Registration #8	2015-04-14	43.984 mi
Registration #9	2016-04-08	47.264 mi
Registration #10	2017-04-08	50.152 mi
Registration #11	2018-04-23	59.274 mi
Registration #12	2018-04-23	59.274 mi
Registration #13	2019-04-23	59.274 mi
Registration #14	2019-04-23	59.274 mi
Registration #15	2019-04-23	59.274 mi
Registration #16	2019-04-23	59.274 mi
Registration #17	2019-04-23	59.274 mi
Registration #18	2019-04-23	59.274 mi
Registration #19	2019-04-23	59.274 mi
Registration #20	2019-04-23	59.274 mi
Registration #21	2019-04-23	59.274 mi
Registration #22	2019-04-23	59.274 mi
Registration #23	2019-04-23	59.274 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1987 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1692 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	4210618