





report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER SD
Colour	Silver
Year of manufacture	2011
Top speed	120 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-06-13

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-14
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	23
Total items failed	2

MOT #13	2024-01-15 13:39
MOT test number	811817208989
Result	✓ Passed
Next expiry date	2025-01-14

MOT #12	2023-06-03 10:37
MOT test number	851457493088
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge both worn	inner edge (5.2.3 (e))

MOT #11	2022-06-06 10:39
MOT test number	501968853951
Result	✓ Passed
MOT #10	2022-02-07 08:02
MOT test number	950798430728
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/13



MOT #9 2020-12-31 15:08

MOT test number 102621697008

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2019-07-12 06:12

MOT test number 918045938416

Result ✓ Passed

MOT #7 2018-07-17 08:10

MOT test number 458703336935

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

Advice Passenger seat(s) missing at time of test rear seats folded flat

Advice Fluid leak, but not excessive coolant (8.4.1 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

CarCheck.co.uk page 4/13



MOT #6 2018-07-17 08:10

MOT test number 700293792571

Result X Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Passenger seat(s) missing at time of test rear seats folded flat

Advice Fluid leak, but not excessive coolant (8.4.1 (a) (i))

MOT #5 2017-07-18 14:56

MOT test number 595322942913

Result \rightarrow Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2016-07-09 11:42

MOT test number 690277568378

Advice Front top mount rubbers starting to come away

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear tyres worn low on inner edges

CarCheck.co.uk page 5/13



MOT test number

Result

Advice Front top mount rubbers starting to come away

Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice Rear tyres worn low on inner edges

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2015-07-14 10:40
MOT test number	198105895138
Result	✓ Passed
MOT #1	2014-06-28 11:08
MOT test number	315999474137
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	14 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date

Category


Type

Damage 2

Date

Category

Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-07-21
Last registration	2024-01-15
Complete history	See info



Registration #1	2011-07-21	12 mi
Registration #2	2014-06-28	48.122 mi
Registration #3	2015-07-14	67.228 mi
Registration #4	2016-07-09	79.126 mi
Registration #5	2016-07-09	79.126 mi
Registration #6	2017-07-18	93.947 mi
Registration #7	2018-07-17	103.591 mi
Registration #8	2018-07-17	103.591 mi
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1345 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	47	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	e 13/13

Number of axles 2

Engine number 71457770