



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO E (55BHP)
Colour	Blue
Year of manufacture	-
Top speed	94 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



MOT history

MOT #20	2022-11-07 20:07
MOT test number	625658925598
Result	✓ Passed
Next expiry date	2023-11-15
Minor	Front Drive shaft joint constant velocity boot severely deteriorated Both front (6.1.7 (g) (i))

MOT #19	2021-11-08 15:50
MOT test number	432010626534
Result	✓ Passed

MOT #18	2021-11-02 12:55
MOT test number	985666546704
Result	✗ Failed

MAJOR Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

MAJOR Brake pedal has insufficient reserve travel (1.1.2 (a))

MAJOR Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

MAJOR Offside Headlamp aim too high (4.1.2 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Front Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))

MAJOR Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MAJOR Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

MAJOR Brake lever has insufficient reserve travel (1.1.2 (a))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Nearside Headlamp aim too low (4.1.2 (a))



MOT #17	2020-10-19 09:44
MOT test number	925970452227
Result	✓ Passed
Advice	Nearside Front Outer cv boot in poor condition
Advice	Long handbrake
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Offside Rear shocker bump stop fallen down
Advice	Nearside Front track rod end in poor condition

MOT #16	2019-11-14 15:31
MOT test number	544672109682
Result	✓ Passed
MOT #15	2019-11-14 15:31
MOT test number	987603531176
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))

**MOT #14**

2019-11-13 11:54

MOT test number

683823397223

Result

✗ Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Offside Rear Lower Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Lower Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13**

2018-10-30 10:05

MOT test number

340607841131

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside front tyre worn on inner edge**MOT #12**

2017-11-16 18:54

MOT test number

422567476814

Result

✓ Passed

Advice Offside Front Tyre worn on inner edge!

**MOT #11** 2017-11-09 17:32**MOT test number** 415512697569**Result** ✗ Failed**Advice** Offside Front Tyre worn on inner edge!**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #10** 2017-02-19 10:34**MOT test number** 695001519705**Result** ✓ Passed**Advice** Child seats fitted in rear seats**Advice** Both front lower arm bushes cracking**MOT #9** 2016-02-27 14:28**MOT test number** 889190164608**Result** ✓ Passed**Advice** Offside Front Front suspension has slight play in a pin or bush of an lower wishbone inner bearing (2.5.B.1a)**Advice** Nearside Front Front suspension has slight play in a pin or bush of an lower wishbone inner bearing (2.5.B.1a)**MOT #8** 2016-02-27 11:41**MOT test number** 929762415900**Result** ✗ Failed**Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Front suspension has slight play in a pin or bush of an lower wishbone inner bearing (2.5.B.1a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Front suspension has slight play in a pin or bush of an lower wishbone inner bearing (2.5.B.1a)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #7	2015-02-14 10:11
MOT test number	169065345047
Result	✓ Passed

MOT #6	2015-02-14 10:11
MOT test number	249105845055
Result	✗ Failed
<div>Pass with rectification Parking brake lever has no reserve travel (3.1.6b)</div>	

MOT #5	2014-02-17 11:10
MOT test number	518398344067
Result	✓ Passed
<div>Notice Nearside rear tyre over five years old and side wall badly cracking</div>	

MOT #4	2013-02-21 12:08
MOT test number	499122753077
Result	✓ Passed
<div>Advice Nearside Front front brake juddering slightly (3.7.A.2b)</div>	

MOT #3	2012-02-24 09:26
MOT test number	486755452044
Result	✓ Passed

MOT #2	2011-02-24 11:41
MOT test number	999665151007
Result	✓ Passed

MOT #1	2010-02-25 15:43
MOT test number	921766650084
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	WU07GWC
Plate since	2019-06-29
Current registration	WU07GWC
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-01
Last registration	2022-11-07
Complete history	See info



Registration #1	2007-03-01	8 mi
Registration #2	2010-02-25	25.807 mi
Registration #3	2011-02-24	29.951 mi
Registration #4	2012-02-24	33.257 mi
Registration #5	2013-02-21	36.004 mi
Registration #6	2014-02-17	38.571 mi
Registration #7	2015-02-14	41.724 mi
Registration #8	2016-02-27	45.643 mi
Registration #9	2016-02-27	45.643 mi
Registration #10	2017-02-19	50.062 mi
Registration #11	2018-02-20	50.062 mi
Registration #12	2019-02-20	50.062 mi
Registration #13	2020-02-20	50.062 mi
Registration #14	2021-02-20	50.062 mi
Registration #15	2022-02-20	50.062 mi
Registration #16	2023-02-20	50.062 mi
Registration #17	2024-02-20	50.062 mi
Registration #18	2025-02-20	50.062 mi
Registration #19	2026-02-20	50.062 mi
Registration #20	2027-02-20	50.062 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1186 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMD194531