





General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Grey
Year of manufacture	2010
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	В





Internet history		
Entry 1		
Date	2021-10-27	
Pictures	0	
Listing price	View report	

source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-09
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	25
Total items failed	7

MOT #14	2023-05-05 14:15
MOT test number	911859124150
Result	🗸 Passed
Next expiry date	2024-05-09
Advice Nearside Front Suspension arm pin or bush worn but not resulting in earbush (5.3.4 (a) (i))	xcessive movement the rear
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in exc bush (5.3.4 (a) (i))	cessive movement the rear
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously wea	akened (1.1.14 (a) (ii))



MOT #13 2023-05-05 09:37 **MOT test number** 285481127217 Result × Failed **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Rear Brake pipe excessively corroded to the flexi brake rubber hose. (1.1.11 (c)) Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Stop lamp(s) not working (4.3.1 (a) (ii)) Fail **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement the rear bush (5.3.4 (a) (i)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Offside Front Service brake binding but not excessively (1.2.1 (f)) Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii)) Fail Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement the rear bush (5.3.4 (a) (i))

MOT #12	2022-05-10 14:58
MOT test number	462618156595
Result	✓ Passed







MOT #11	2021-05-08 06:54
MOT test	number 926765731136
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2020-02-22 14:31
MOT test number	634266134052
Result	✓ Passed

МОТ #9	2020-02-22 13:07
MOT test number	234294161099
Result	🗙 Failed
Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))	

 MOT #8
 2019-08-08 08:20

 MOT test number
 591313910398

 Result
 Image: Passed

 Advice
 Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

 Advice
 Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

МОТ #7	2018-08-06 14:15
MOT test number	861372840179
Result	✓ Passed



BN60ZUA report date: 2024-03-29

MOT #6	2017-08-09 13:51
MOT test number	270156582969
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #5	2017-08-09 09:33
MOT test number	858564646466
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside front brake binding (3.7.B.1)	

МОТ #4	2016-08-10 10:58
MOT test number	359885139313
Result	✓ Passed

MOT #3	2015-08-17 14:16
MOT test number	281873660692
Result	✓ Passed

MOT #2	2014-09-08 17:13
MOT test number	338581554248
Result	✓ Passed

MOT #1	2013-09-23 15:53
MOT test number	386956463224
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	



BN60ZUA report date: 2024-03-29

Tax & MOT check

Tax due: 1 May 2024	✓ Taxed	Expires: 9 May 2024	✓ мот
Tax status			Valid until 1 May
Days left			3
MOT expiry date			9 May 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



BN60ZUA report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-27
Last registration	2023-05-05
Complete history	See info



Registration #1	2010-09-27	20 mi
Registration #2	2013-09-23	14.980 mi
Registration #3	2014-09-08	20.097 mi
Registration #4	2015-08-17	23.209 mi
Registration #5	2016-08-10	29.248 mi
Registration #6	2017-08-09	35.339 mi
Registration #7	2017-08-09	35.339 mi
Registration #8	2018-08-06	41.819 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		10.307 est

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	112085