





report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 HDI SW SR
Colour	Silver
Year of manufacture	-
Top speed	126 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-28

MOT history

Advice

MOT test number

Result

Next expiry date

Advice

Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

Nearside headlamp loose at inside mount

MOT #12

MOT test number

Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT test number

160508246949

Result

Minor Offside Rear Tyre obviously under inflated has nail in tyre (5.2.3 (h) (i))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #10

MOT test number

620732653808

Result

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Offside Rear Nail in tyre

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT test number
933836840464

Result

Advice Offside Rear Nail in tyre

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT test number

Result

Advice

Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice

Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #7	2017-01-27 11:23
MOT test number	738302862232
Result	× Failed
Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Fail Offside Headlamp not working on dipped beam (1.7.5a)	
Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A'	'(8.3.1d)
Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	

CarCheck.co.uk page 3/11



report date: 2024-03-28

 MOT #6
 2016-02-11 16:17

 MOT test number
 292643150899

 Result
 ✓ Passed

 MOT #5
 2016-02-11 12:30

 MOT test number
 559658258542

 Result
 X Failed

 Fail
 Offside rear brake binding (3.7.B.1)

MOT #4

MOT test number

Result

Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

Notice Front tyres worn on inner edges

MOT test number

645171055095

Result

Notice Front tyres worn on inner edges

Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

Fail Nearside Rear fog lamp does not emit a steady red light (1.3.2e)

MOT test number

Result

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT #1

MOT test number

186109543443

Result

Notice Front tyres wearing on inner edges

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK SILE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-02-23
Last registration	2020-01-23
Complete history	See info



Registration #1	2010-02-23	22 mi
Registration #2	2013-02-18	29.667 mi
Registration #3	2014-01-29	48.524 mi
Registration #4	2015-02-20	60.982 mi
Registration #5	2015-02-20	60.983 mi
Registration #6	2016-02-11	70.688 mi
Registration #7	2016-02-11	70.691 mi
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		0.07 66

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1494 mm
Length	4763 mm
Wheel base	2725 mm
Kerb weight	1612 kg
Max. allowed weight	2195 kg

Additional information

Fuel tank capacity	66 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number DYXH4103212