



AJ64KXT


report date: 2024-03-28

General information

Make	AUDI
Model	A1 TDI S LINE
Colour	Blue
Year of manufacture	2015
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-06-14
Pictures	0
Listing price	View report

source: yesauto.com

Entry 1

Date	2021-06-03
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-18
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	24
Total items failed	6

MOT #12 2023-08-17 14:44

MOT test number 273057720863

Result ✓ Passed

Next expiry date 2024-08-18

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
REAR BUSH (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
REAR BUSH (5.3.4 (a) (i))

MOT #11 2023-08-17 11:09

MOT test number 720260654536

Result ✗ Failed

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt
(5.3.4 (b) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
REAR BUSH (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MAJOR Nearside Headlamp insecure (4.1.1 (c))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
REAR BUSH (5.3.4 (a) (i))

**MOT #10**

2022-08-19 07:34

MOT test number

384865644628

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear fouling fuel tank breather**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2022-08-05 08:58

MOT test number

226647644054

Result

✗ Failed

Advice Nearside Front brake flexi insecure**DANGEROUS** Offside Front Lower Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front spring adjuster loose**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front brake flexi fouling wheel**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear fouling fuel tank breather**DANGEROUS** Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))**MOT #8**

2021-07-26 13:53

MOT test number

318079337207

Result

✓ Passed

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2020-11-12 16:25**MOT test number** 396391367236**Result** ✓ Passed**MOT #6** 2020-11-12 16:25**MOT test number** 925057935502**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MOT #5** 2019-11-13 16:22**MOT test number** 875980842430**Result** ✓ Passed**MOT #4** 2019-11-13 16:22**MOT test number** 745955255858**Result** ✗ Failed**Pass with rectification** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Pass with rectification** Tyre tread depth below requirements of 1.6mm both rear (5.2.3 (e))**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #3** 2018-11-01 17:23**MOT test number** 825533235912**Result** ✓ Passed**MOT #2** 2017-11-27 12:06**MOT test number** 728643013709**Result** ✓ Passed



MOT #1	2017-11-27 12:06
MOT test number	374814474886
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
18 August 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	18 August 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-01-30
Last registration	2023-08-17
Complete history	See info



Registration #1	2015-01-30	6 mi
Registration #2	2017-11-27	26.621 mi
Registration #3	2017-11-27	26.621 mi
Registration #4	2018-11-01	44.116 mi
Registration #5	2019-11-13	60.728 mi
Registration #6	2019-11-13	60.728 mi
Registration #7	2020-11-12	71.595 mi
Registration #8	2020-11-12	71.595 mi
Registration #9	2020-11-12	71.595 mi
Registration #10	2020-11-12	71.595 mi
Registration #11	2020-11-12	71.595 mi
Registration #12	2020-11-12	71.595 mi
Registration #13	2020-11-12	71.595 mi
Registration #14	2020-11-12	71.595 mi
Registration #15	2020-11-12	71.595 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	79%
Pedestrian	49%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1740 mm
Height	1416 mm
Length	3954 mm
Wheel base	2469 mm
Kerb weight	1140 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	CAYCU83365