





General information

Make	MAZDA
Model	3 TAKARA
Colour	Blue
Year of manufacture	2009
Top speed	114 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history	
Entry 1	
Date	2021-06-16
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-14
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	34
Total items failed	0

MOT #15	2023-06-10 09:43
MOT test number	680568967397
Result	✓ Passed
Next expiry date	2024-06-14
Advice Surface corrosion under vehicle	

MOT #14 2022-06-08 07:35 **MOT test number** 895823004742 Result Passed Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i)) Advice Surface corrosion under vehicle Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Front discs in poor condition Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13	2021-06-15 17:31
MOT test number	253876604542
Result	✓ Passed





MOT #12		2021-06-15 13:06
MOT test	number	340608677256
Result		🗙 Failed
MAJOR	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
MOT #11		2020-05-27 08:27
MOT test	number	791421181406
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn trailing arm bush (5.1.2 (b) (i))		
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn trailing arm bush (5.1.2 (b) (i))		
Advice	Headlight washers not working	
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Central Front Brake disc worn, but not excessively (1.1.14 (a) (i))	



BK09HXP report date: 2024-03-29

MOT #10	2020-05-22 16:13
MOT test	number 577520412564
Result	× Failed
Advice	Central Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Headlight washers not working
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice (5.1.2 (b)	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn trailing arm bush (i))
DANGER	ROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
MAJOR (5.2.3 (d)	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (i))
MAJOR	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Nail in tyre inner shoulder
Advice (5.1.2 (b)	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn trailing arm bush (i))
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Central Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR (5.2.3 (d)	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (i))
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))

МОТ #9	2019-05-02 11:47
MOT test number	910242377308
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	



ВКО9НХ	Ρ
report date: 2024-0	3-29

MOT #8	2018-04-24 08:55
MOT test number	584567852246
Result	Passed
Advice Offside Front Suspension arm rubber bush deteriorated but not re Trailing wishbone bush. (2.4.G.2)	esulting in excessive movement
Advice Nearside Front Suspension arm rubber bush deteriorated but not Trailing wishbone bush. (2.4.G.2)	resulting in excessive movement
MOT #7	2017-04-26 11:42
MOT test number	179573265735
Result	✓ Passed
МОТ #6	2016-04-09 07:13
MOT test number	268611592897
Result	√ Passed
МОТ #5	2016-04-08 09:27
MOT test number	259058065163
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit worn on inner edge	ge and low on pressure (4.1.E.1)
MOT #4	2015-04-02 11:07
MOT test number	625742195018
Result	✓ Passed
MOT #3	2014-04-07 09:03
MOT test number	159087094469
Result	✓ Passed
	•
MOT #2	2013-04-17 10:05
MOT test number	889207603144
Result	✓ Passed





MOT #1	2012-04-28 10:57
MOT test number	538859012175
Result	✓ Passed



Tax & MOT check

✓ Taxed	√ мот
Tax due: 1 July 2024	Expires: 14 June 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. ALANPE
Туре	
Damage 2	AMPL
Damage 2	E CUT-S
Date	14 N
Category	AMP
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes See in this check if this MAZDA had different number plates.	
Rumber of plates	
Current registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



BK09HXP report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-30
Last registration	2023-06-10
Complete history	See info



Registration #1	2009-03-30	9 mi
Registration #2	2012-04-28	19.033 mi
Registration #3	2013-04-17	28.173 mi
Registration #4	2014-04-07	35.409 mi
Registration #5	2015-04-02	44.502 mi
Registration #6	2016-04-08	52.328 mi
Registration #7	2016-04-09	52.328 mi
Registration #8	2017-04-26	60.973 mi
Registration #9	2018-04-24	65.841 mi
Registration #10		11.777 esi
Registration #11		11.777 est
Registration #12		11.777 esi
Registration #13		11.777 est
Registration #14		11.777 esi
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		
Registration #17		



BK09HXP report date: 2024-03-29

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1755 mm
Height	1465 mm
Length	4440 mm
Wheel base	2640 mm
Kerb weight	1275 kg
Max. allowed weight	1725 kg
Additional information	
Additional information Fuel tank capacity	55 I
	55 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5