



report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE D XS
Colour	Black
Year of manufacture	-
Top speed	143 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	206 BHP
Max. torque	435 Nm at 1.900 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-13
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #17	2022-02-08 17:35
MOT test number	390445550926
Result	✓ Passed
Next expiry date	2023-02-07

MOT #16	2021-05-04 15:29
MOT test number	208455663201
Result	✓ Passed

MOT #15	2020-10-26 20:13
MOT test number	177042595932
Result	✓ Passed

MOT #14	2020-06-05 09:19
MOT test number	832462605598
Result	✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2019-06-10 10:00
MOT test number	360281554103
Result	✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #12	2018-06-09 10:25
MOT test number	736762328413
Result	✓ Passed

**MOT #11** 2017-06-13 12:55**MOT test number** 641690494214**Result** ✓ Passed**MOT #10** 2016-11-08 09:29**MOT test number** 663490395843**Result** ✓ Passed**Advice** Nearside and offside front track rod end have corrosion**MOT #9** 2015-11-23 10:09**MOT test number** 883246703111**Result** ✓ Passed**Advice** Off side and near side front tyres going bald inner edges**MOT #8** 2014-11-25 16:35**MOT test number** 177269124346**Result** ✓ Passed**Notice** Both front tyres getting low on the inner edges**MOT #7** 2014-11-24 11:17**MOT test number** 757618724333**Result** ✗ Failed**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Nearside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Notice** Both front tyres getting low on the inner edges**MOT #6** 2013-11-18 10:20**MOT test number** 427202323418**Result** ✓ Passed



MOT #5	2012-11-21 14:04
---------------	------------------

MOT test number	425346922313
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2011-11-22 10:10
---------------	------------------

MOT test number	136906221374
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2011-11-22 10:10
---------------	------------------

MOT test number	615276121377
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	---

Pass with rectification	Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)
--------------------------------	---

MOT #2	2010-11-24 12:07
---------------	------------------

MOT test number	883178520343
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-03-12 10:03
---------------	------------------

MOT test number	224941270018
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-29
Last registration	2022-02-08
Complete history	See info



Registration #1	2007-03-29	15 mi
Registration #2	2010-03-12	43.410 mi
Registration #3	2010-11-24	51.174 mi
Registration #4	2011-11-22	53.296 mi
Registration #5	2012-11-21	55.129 mi
Registration #6	2013-11-18	56.639 mi
Registration #7	2014-11-24	58.286 mi
Registration #8	2014-11-25	58.286 mi
Registration #9	2015-11-23	59.324 mi
Registration #10	2016-05-20	60.377 mi
Registration #11	2016-05-20	60.377 mi
Registration #12	2016-05-20	60.377 mi
Registration #13	2016-05-20	60.377 mi
Registration #14	2016-05-20	60.377 mi
Registration #15	2016-05-20	60.377 mi
Registration #16	2016-05-20	60.377 mi
Registration #17	2016-05-20	60.377 mi
Registration #18	2016-05-20	60.377 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2060 mm
Height	1447 mm
Length	4905 mm
Wheel base	2909 mm
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	02224317G