



General information

Make	MINI
Model	MINI (R57) COOPER D
Colour	Red
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.3 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2023-11-24
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	10
Total items failed	3

MOT #10	2022-11-25 09:10
MOT test number	329003463536
Result	✓ Passed
Next expiry date	2023-11-24

MOT #9	2022-07-20 09:26
MOT test number	284505211473
Result	✓ Passed
Advice	Front Inner Tyre worn close to legal limit/worn on edge 2 (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened front subframe slightly corroded. (1.1.14 (a) (ii))

MOT #8	2021-07-28 14:52
MOT test number	747697010108
Result	✓ Passed

MOT #7	2021-07-26 08:53
MOT test number	106209368366
Result	✗ Failed
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #6** 2018-04-30 13:02**MOT test number** 206444781219**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2017-04-06 06:45**MOT test number** 840987253176**Result** ✓ Passed**MOT #4** 2017-04-05 12:39**MOT test number** 554632249682**Result** ✗ Failed**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**Advice** O/s/front brake disc looks to have got hot(poss due to bind).**Fail** Offside front brake binding (3.7.B.1)**MOT #3** 2016-05-20 12:35**MOT test number** 505307124449**Result** ✓ Passed**Advice** Advisory under tray and engine cover fitted**Advice** Registration plate deteriorated but not likely to be misread front (6.3.1d)**MOT #2** 2015-06-18 14:52**MOT test number** 585109665173**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #1	2015-06-18 14:52
MOT test number	789249165104
Result	✗ Failed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-07-19
Last registration	2022-11-25
Complete history	See info



Registration #1	2012-07-19	15 mi
Registration #2	2015-06-18	48.032 mi
Registration #3	2016-05-20	64.225 mi
Registration #4	2017-04-05	69.505 mi
Registration #5	2017-04-06	69.505 mi
Registration #6	2018-04-30	77.450 mi
Registration #7	2019-05-20	85.377 mi
Registration #8	2019-05-20	85.377 mi
Registration #9	2019-05-20	85.377 mi
Registration #10	2019-05-20	85.377 mi
Registration #11	2019-05-20	85.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1200 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number

70858233