





report date: 2024-03-29

General information

Make	FIAT
Model	500 C POP
Colour	White
Year of manufacture	2011
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2022-04-14

Pictures 18

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2022-04-12

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

140	
10/1/1	Γ history
י אועו	1 11151017

Fail

MOT expiry date	2025-01-30
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	8
Total items failed	9

MOT #13	2024-01-31 11:08
MOT test number	144731957823
Result	✓ Passed
Next expiry date	2025-01-30

MOT #12	2023-01-31 09:58
MOT test number	706891215652
Result	✓ Passed

MOT #11	2022-01-31 15:25
MOT test number	843822903791
Result	✓ Passed

MOT #10	2022-01-28 08:54

Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9 2019-05-10 14:36

MOT test number 603376476219

Result \rightarrow Passed

Advice

Brake disc worn, pitted or scored, but not seriously weakened Both sides front (1.1.14 (a) (ii))

MOT #8 2018-06-01 14:31

MOT test number 577252778763

Result \(\sqrt{Passed} \)

MOT #7 2018-05-31 15:53

MOT test number 973201150626

Result X Failed

Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Fail Offside Rear Shock absorbers likely to become detached (5.3.2 (a) (ii))

Fail Nearside Rear Shock absorbers likely to become detached (5.3.2 (a) (ii))

MOT #6 2017-09-08 12:11

MOT test number 449297413416

Result
✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

MOT #5 2017-09-02 09:45

MOT test number 888862903897

Result × Failed

Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2016-09-03 10:00

MOT test number 833363044770

Result ✓ Passed

MOT #3 2015-09-08 09:11

MOT test number 654168665870

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2014-09-06 13:01

MOT test number 365039944425

Result \rightarrow Passed

MOT #1 2014-09-06 12:05

MOT test number 675969844220

Result X Failed

Notice Vehicle's internal headlight adjuster altered to recheck lights

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 5/12



WV61MVK report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-08
Last registration	2024-01-31
Complete history	See info



Registration #1	2011-09-08	27 mi
Registration #2	2014-09-06	20.916 mi
Registration #3	2014-09-06	20.916 mi
Registration #4	2015-09-08	28.028 mi
Registration #5	2016-09-03	34.812 mi
Registration #6	2017-09-02	40.784 mi
Registration #7	2017-09-08	40.869 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number0012511