



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Grey
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-10
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #16</b>	2022-10-17 13:00
<b>MOT test number</b>	932304408533
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-10-18
<b>Advice</b>	Rear Passenger seat(s) missing at time of test rearmost seats folded - belts not inspected

<b>MOT #15</b>	2021-10-07 14:23
<b>MOT test number</b>	507234497063
<b>Result</b>	✓ Passed

<b>MOT #14</b>	2020-10-19 08:06
<b>MOT test number</b>	955097764947
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Rear Exhaust mounting defective (6.1.2 (a))
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))

<b>MOT #13</b>	2019-06-24 10:03
<b>MOT test number</b>	352630294105
<b>Result</b>	✓ Passed

**MOT #12**

2018-06-21 09:15

**MOT test number**

903580076080

**Result**

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11**

2017-06-30 13:33

**MOT test number**

805774414907

**Result**

✓ Passed

**MOT #10**

2016-06-01 09:34

**MOT test number**

687960027894

**Result**

✓ Passed

**MOT #9**

2016-05-27 08:56

**MOT test number**

873627951710

**Result**

✗ Failed

- Fail** Nearside Rear Suspension arm rubber mounting bonding deteriorated resulting in excessive movement (2.4.G.2)
- Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**MOT #8** 2015-07-15 14:54**MOT test number** 317266595158**Result** ✓ Passed

**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** N/s/r tyre has cuts in tread

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Notice** O/s/r tyre worn on inner edge and has cuts in outer wall

**MOT #7** 2015-07-15 14:54**MOT test number** 535226395192**Result** ✗ Failed

**Notice** N/s/r tyre has cuts in tread

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Notice** O/s/r tyre worn on inner edge and has cuts in outer wall

**Pass with rectification** Rear registration plate delaminated (6.3.1d)

**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2014-06-25 16:16**MOT test number** 126556774148**Result** ✓ Passed

**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #5** 2014-06-25 16:16**MOT test number** 869916574157**Result** ✗ Failed

**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)

**MOT #4** 2013-06-11 09:21**MOT test number** 515852363189**Result** ✓ Passed**MOT #3** 2012-06-14 10:54**MOT test number** 828166262157**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-06-14 10:54**MOT test number** 206416762475**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-06-10 10:31**MOT test number** 435721161143**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-07-10
Last registration	2022-10-17
Complete history	<a href="#">See info</a>



Registration #1	2008-07-10	13 mi
Registration #2	2011-06-10	30.931 mi
Registration #3	2012-06-14	42.000 mi
Registration #4	2013-06-11	53.906 mi
Registration #5	2014-06-25	69.140 mi
Registration #6	2015-07-15	82.621 mi
Registration #7	2016-05-27	93.119 mi
Registration #8	2016-06-01	93.120 mi
Registration #9	2016-06-01	93.120 mi
Registration #10	2016-06-01	93.120 mi
Registration #11	2016-06-01	93.120 mi
Registration #12	2016-06-01	93.120 mi
Registration #13	2016-06-01	93.120 mi
Registration #14	2016-06-01	93.120 mi
Registration #15	2016-06-01	93.120 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1943 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

**Engine number**

8C31868