





report date: 2024-03-28

General information

Make	BMW
Model	X3 SE
Colour	Blue
Year of manufacture	2004
Top speed	129 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	192 BHP
Max. torque	245 Nm at 3.500 rpm
Engine capacity	2.494 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.1 mpg
Consumption extra urban	32.5 mpg
Consumption combined	25.2 mpg
CO2 emission	272 g/km
CO2 label	М



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date 2022-01-22

Pictures 36

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-01-29
Pictures	10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-23
MOT pass rate	94 %
MOT passed	17
Failed MOT tests	1
Total advice items	19
Total items failed	3

MOT #18	2024-01-06 13:06
MOT test number	289914200940
Result	✓ Passed
Next expiry date	2025-01-23

MOT #17	2023-01-21 11:11
MOT test number	822025233458
Result	√ Passed

MOT #16		2022-01-24 16:15
MOT test number		116199549533
Result		✓ Passed
Advice Engine cover an	nd under tray	
Advice Rear sub frame	has surface rust on	
Minor Windscreen dam	naged but not adversely affecting driver	's view (3.2 (a) (i))

CarCheck.co.uk page 3/13



DX54YCU

report date: 2024-03-28

MOT #15 2021-03-04 15:17

MOT test number 440128389821

Result ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #14 2020-03-06 09:40

MOT test number 769964251979

Result

Passed

MOT #13 2019-03-15 09:15

MOT test number 258648063570

Result ✓ Passed

MOT #12 2018-03-13 16:53

MOT test number 729109727190

Result
✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #11 2017-03-17 16:34

MOT test number 796805650813

Result ✓ Passed

MOT #10 2016-03-18 16:34

MOT test number 223904338866

Result ✓ Passed

CarCheck.co.uk page 4/13



DX54YCU

report date: 2024-03-28

MOT #9

MOT test number

395818675079

Result

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

Result

Notice

N/s/r tyre cut but not down to cords or ply

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice

Under-trays fitted obscuring some underside components

MOT #7

MOT test number

619663873065

Result

Notice

N/S/R coil spring fractured but spring is locating correctly

Notice

N/S/R tyre has a cut in the tread but not deep enough to reach the ply or cords

 MOT #6
 2012-03-20 16:32

 MOT test number
 398260682093

 Result
 ✓ Passed

 MOT #5
 2011-03-07 16:41

 MOT test number
 639876661033

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



DX54YCU

report date: 2024-03-28

MOT #4	2010-03-04 15:58
MOT test number	970453960069
Result	✓ Passed
MOT #3	2009-03-10 16:16
MOT test number	814119369097
Result	✓ Passed
MOT #2	2009-03-09 16:45
MOT test number	754658969087
Result	× Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #1		2008-03-12 17:06
MOT test	number	561402478069
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)		king system requires
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
THE STATE OF THE S	

THE PARTY OF THE P	

	More info >
	Piore inio /
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK SILVE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-12-24
Last registration	2024-01-06
Complete history	See info



Registration #1	2004-12-24	10 mi
Registration #2	2008-03-12	20.617 mi
Registration #3	2009-03-09	25.919 mi
Registration #4	2009-03-10	25.929 mi
Registration #5	2010-03-04	31.059 mi
Registration #6	2011-03-07	35.995 mi
Registration #7	2012-03-20	40.115 mi
Registration #8	2013-03-14	44.635 mi
Registration #9	2014-03-18	49.570 mi
Registration #10	2015-03-19	55.863 mi
Registration #11	2016-03-18	62.691 mi
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		71.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		71.777 es
Registration #20		71.777 es
Registration #21		

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
S0569	

Dimensions & weight

Width	1853 mm
Height	1674 mm
Length	4565 mm
Wheel base	2795 mm
Kerb weight	1815 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	67 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	21575742

CarCheck.co.uk page 13/13