




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE TSI
Colour	White
Year of manufacture	2015
Top speed	111 mph
0 - 100 km/h	10.9 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	175 Nm at 1.500 rpm
Engine capacity	1.197 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-11-29
Pictures	60
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-11-17
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	4
Total items failed	7

MOT #9	2023-10-26 13:05
MOT test number	293730024925
Result	✓ Passed
Next expiry date	2024-11-17

MOT #8	2022-11-09 11:54
MOT test number	538887835964
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2021-11-18 09:20
MOT test number	235314394277
Result	✓ Passed

**MOT #6** 2021-11-17 11:11**MOT test number** 613320513288**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #5** 2021-03-26 11:33**MOT test number** 586182616582**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2020-03-20 09:29**MOT test number** 450999182627**Result** ✓ Passed**MOT #3** 2019-03-14 12:34**MOT test number** 463098892003**Result** ✓ Passed



MOT #2	2019-03-12 16:04
MOT test number	934445307100
Result	✗ Failed
<div>Fail</div> Nearside Side repeater not working in mirror (4.4.1 (a) (ii))	

MOT #1	2018-03-27 15:20
MOT test number	388512346129
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
17 November 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	17 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 PK15FBE
Plate since	2019-03-29
Current registration	 PK15FBE
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-30
Last registration	2023-10-26
Complete history	See info



Registration #1	2015-03-30	9 mi
Registration #2	2018-03-27	79.654 mi
Registration #3	2019-03-12	115.625 mi
Registration #4	2019-03-14	115.625 mi
Registration #5	2020-03-20	154.063 mi
Registration #6	2021-03-26	168.092 mi
Registration #7	2023-10-26	168.092 mi
Registration #8	2023-10-26	168.092 mi
Registration #9	2023-10-26	168.092 mi
Registration #10	2023-10-26	168.092 mi
Registration #11	2023-10-26	168.092 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2021 mm
Height	1486 mm
Length	4278 mm
Wheel base	2537 mm
Kerb weight	1274 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CBZBH25596