



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 DRIVE SE START/STOP
Colour	Grey
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-12-17
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-30
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	16
Total items failed	0

MOT #10	2023-10-11 11:18
MOT test number	803698491860
Result	✓ Passed
Next expiry date	2024-10-10

MOT #9	2022-09-07 08:33
MOT test number	238204257245
Result	✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #8	2021-10-04 14:43
MOT test number	365172675598
Result	✓ Passed

**MOT #7**

2021-01-18 15:00

MOT test number

343900369315

Result

✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened scored (1.1.14 (a) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front trailing arm bush starting to show signs of perishing (5.3.4 (a) (i))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge starting to show signs of flat spotting (5.2.3 (e))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front trailing arm bush starting to show signs of perishing (5.3.4 (a) (i))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge edge starting to show signs of flat spotting (5.2.3 (e))

Advice Covers fitted underneath and in engine bay restricting the view of some testable components

MOT #6

2019-07-10 10:13

MOT test number

377793894229

Result

✓ Passed

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement TRAILING ARM FRONT BUSH (5.3.4 (a) (i))

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement TRAILING ARM FRONT BUSH (5.3.4 (a) (i))

MOT #5

2018-07-18 13:55

MOT test number

217445877609

Result

✓ Passed

Advice Exhaust corroded

Advice Engine cover and Undertrays fitted



MOT #4	2017-07-18 12:43
MOT test number	191888585797
Result	✓ Passed
MOT #3	2017-01-11 09:45
MOT test number	596730644011
Result	✓ Passed
MOT #2	2016-01-27 10:08
MOT test number	452952102121
Result	✓ Passed
MOT #1	2015-03-03 10:47
MOT test number	827442765058
Result	✓ Passed
Advice	Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
10 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-31
Last registration	2023-10-11
Complete history	See info



Registration #1	2012-03-31	25 mi
Registration #2	2015-03-03	93.151 mi
Registration #3	2016-01-27	95.169 mi
Registration #4	2017-01-11	100.471 mi
Registration #5	2017-07-18	101.791 mi
Registration #6	2018-07-18	111.116 mi
Registration #7	2019-07-10	118.331 mi
Registration #8	2020-05-20	121.277 mi
Registration #9	2021-05-20	121.277 mi
Registration #10	2022-05-20	121.277 mi
Registration #11	2023-05-20	121.277 mi
Registration #12	2024-05-20	121.277 mi
Registration #13	2025-05-20	121.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1582 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4130882