

Ø



General information

Make	LEXUS
Model	NX 300H
Colour	Silver
Year of manufacture	2019
Top speed	112 mph
Gearbox	1 speed automatic

Engine & fuel consumption

Power	194 BHP	0 < 101 A
Max. torque	480 Nm at 4.200 rpm	101 - 120 ^B _C
Engine capacity	2.494 cc	121 - 140 P
Cylinders	4	141 - 165 F G
Fuel type	Hybrid / Electric	166 - 185 H
Consumption combined	37.2 mpg	186 - 225 J
CO2 emission	137 g/km	225+
CO2 label	E	





Internet history

Entry 1	
Date	2021-06-13
Pictures	26
Listing price	View report









source: yesauto.com



MOT history

MOT expiry date	2024-09-29
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	3
Total items failed	0

MOT #3	2023-09-27 15:41
MOT test number	699764284995
Result	✓ Passed
Next expiry date	2024-09-29

MOT #2	2023-09-27 08:22
MOT test number	453965160933
Result	🗙 Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #1	2022-09-21 11:10
MOT test number	396945903965
Result	✓ Passed



Tax & MOT check

Taxed Tax due: 1 November 2024	✓ MOT Expires: 29 September 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	н
First licence fee (12 months)	£ 245,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-





Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Anne
Туре	K K
Damage 2	AMPLE
Damage 2	e et - I - I
Date	S.
Category	AMPT
Туре	

Extra LEXUS salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this LEXUS had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles	
Mileage registrations	5	
First mileage registration	2019-09-30	
Last registration	2023-09-27	
Complete history	See info	



Registration #1	2019-09-30	7 mi
Registration #2		11.777 est
Registration #3	2022-09-21	23.163 mi
Registration #4		11.777 est
Registration #5		10.317 mi





Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	82%
Children	82%
Pedestrian	69%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight	
Width	1845 mm
Height	1645 mm
Length	4640 mm
Max. allowed weight	2395 kg
Additional information	
Number of seats	5
Number of axles	2

2AR2188203

Engine number