



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MOVANO F3500 L2H2 P/V CDTI
Colour	Silver
Year of manufacture	2013
Top speed	134 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	285 Nm at 1.250 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	37.7 mpg
Consumption combined	34.0 mpg
CO2 emission	205 g/km
CO2 label	K





## MOT history

MOT expiry date	2025-02-15
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	22
Total items failed	10

**MOT #13** 2024-02-16 09:51**MOT test number** 370240340296**Result** ✓ Passed**Next expiry date** 2025-02-15**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2024-02-16 09:51**MOT test number** 673160180006**Result** ✗ Failed**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #11**

2023-02-15 10:11

**MOT test number**

384391751557

**Result**

✓ Passed

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge Also wear on inner and outer tread (5.2.3 (e))

**Minor**

Nearside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #10**

2021-09-03 14:41

**MOT test number**

362555972462

**Result**

✓ Passed

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice**

Brake pedal anti slip deteriorated but still secure

**MOT #9**

2021-08-25 12:04

**MOT test number**

971013461206

**Result**

✗ Failed

**Fail**

Nearside Headlamp aim too low slightly too low (4.1.2 (a))

**Advice**

Offside Rear handbrake performance low

**Fail**

Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**Advice**

Nearside Rear Brake pad(s) wearing thin cannot clearly see any other brake pads to assess wear (1.1.13 (a) (ii))

**Fail**

Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail**

Offside Headlamp aim too low and no real beam pattern (4.1.2 (a))

**Advice**

Brake pedal anti slip deteriorated but still secure

**Fail**

Central Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))



<b>MOT #8</b>	2020-08-24 11:08
<b>MOT test number</b>	997935326632
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside front lower suspension arm ball joint gaiter deteriorated

<b>MOT #7</b>	2019-09-03 12:43
<b>MOT test number</b>	268529649007
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside front brake warning wire broken
<b>Advice</b>	Nearside rear tyre perished & wearing on outer edge
<b>Advice</b>	Nearside front outer CV gaiter deteriorating & leaking grease
<b>Advice</b>	Offside rear brake has a slight bind when rotated by hand
<b>Advice</b>	Offside rear handbrake lever off of its stop

<b>MOT #6</b>	2018-09-04 13:48
<b>MOT test number</b>	541549108647
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front pad wear warning wiring damaged

<b>MOT #5</b>	2018-09-03 08:38
<b>MOT test number</b>	764281636030
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
<b>Advice</b>	Nearside Front pad wear warning wiring damaged
<b>Fail</b>	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #4** 2017-08-28 07:15**MOT test number** 615535523531**Result** ✓ Passed**MOT #3** 2017-08-28 07:15**MOT test number** 229172876187**Result** ✗ Failed**Pass with rectification** Central Rear Upper Stop lamp not working (1.2.1b)**MOT #2** 2016-09-02 09:28**MOT test number** 893698552313**Result** ✓ Passed**MOT #1** 2016-09-02 07:12**MOT test number** 694637042850**Result** ✗ Failed**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)



Tax & MOT check

X

Untaxed

Tax expired:  
1 March 2024

✓

MOT

Expires:  
15 February 2025

Tax status	Expired at 1 March 2024
Days left	58 days too late
MOT expiry date	15 February 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>SN63FBA</b>
Plate since	2024-03-28
Current registration	<b>SN63FBA</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-04
Last registration	2024-02-16
Complete history	<a href="#">See info</a>



Registration #1	2013-09-04	23 mi
Registration #2	2016-09-02	31.302 mi
Registration #3	2016-09-02	31.302 mi
Registration #4	2017-08-28	41.714 mi
Registration #5	2017-08-28	41.714 mi
Registration #6	2018-09-03	52.786 mi
Registration #7	2018-09-04	52.794 mi
Registration #8	2019-09-02	52.794 mi
Registration #9	2019-09-02	52.794 mi
Registration #10	2019-09-02	52.794 mi
Registration #11	2019-09-02	52.794 mi
Registration #12	2019-09-02	52.794 mi
Registration #13	2019-09-02	52.794 mi
Registration #14	2019-09-02	52.794 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2470 mm
Height	2500 mm
Length	5548 mm
Kerb weight	1890 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	M9T -C064461 LWK