





report date: 2024-03-28

## General information

Make	PEUGEOT
Model	107 URBAN
Colour	Grey
Year of manufacture	2011
Top speed	98 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/12



## Internet history

## Entry 1

Date 2021-06-18

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



## MOT history

MOT expiry date	2024-05-29
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	22
Total items failed	0

MOT #12	2023-05-30 15:04
MOT test number	137453389340
Result	<b>✓</b> Passed
Next expiry date	2024-05-29

MOT #11	2023-05-30 10:26
MOT test number	797983984338
Result	🗙 Failed
Minor  (i))  Offside Registration plate lamp inoperative in the case of multiple lamps or light	t sources (4.7.1 (b)
<b>DANGEROUS</b> Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2021-11-17 13:35
MOT test number	626080119179
Result	<b>✓</b> Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #9 2021-11-17 10:19

MOT test number 298959507277

**Result** X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Offside Brake pipe excessively corroded front to rear .. rear section (1.1.11 (c))

**MAJOR** Nearside Brake pipe excessively corroded front to rear .. rear section (1.1.11 (c))

MOT #8 2020-11-24 13:22

MOT test number 345203394713

Result / Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Perished outer wall & in tread (5.2.3

Advice Offside Front Tyre slightly damaged/cracking or perishing Perished outer wall & in tread (5.2.3 (d)

MOT #7 2019-11-25 15:27

MOT test number 144041791049

Result 

Passed

**Advice** Handbrake travel high

(d) (ii))

(ii))

Advice Rear Exhaust has a minor leak of exhaust gases and rusty brackets (6.1.2 (a))

Advice Rear Brake pipe corroded, covered in grease or other material rusty (1.1.11 (c))

MOT #6 2018-11-29 15:22

MOT test number 310665414943

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #5 2018-11-29 11:36

**MOT test number** 153410624219

**Result** X Failed

MAJOR Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2017-09-26 13:11

MOT test number 567944263642

Result \sqrt{Passed}

Advice Exhaust has a minor leak of exhaust gases joint between centre section and rear silencer (7.1.2)

**Advice** Offside Rear Tyre worn close to the legal limit worn on inner and outer edges (4.1.E.1)

**Advice** Offside Rear Brake pipe slightly corroded front to rear to flexible hose (3.6.B.2c)

**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Brake pipe slightly corroded front to rear from ABS pump (3.6.B.2c)

MOT #3 2016-09-10 09:04

MOT test number 506142001858

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #2 2015-08-25 11:32

**MOT test number** 839907435242

Result \rightarrow Passed

**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #1 2014-09-19 11:17

**MOT test number** 877792964230

Result 

Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	29 May 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



$\sim$	
Owner	nictory
CVVIICI	IIISLUIV
~	,

e which misterly	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	AIR SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



## Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-12-30
Last registration	2023-05-30
Complete history	See info



Registration #1	2011-12-30	10 mi
Registration #2	2014-09-19	22.277 mi
Registration #3	2015-08-25	28.093 mi
Registration #4	2016-09-10	37.447 mi
Registration #5	2017-09-26	50.909 mi
Registration #6	2018-11-29	56.775 mi
Registration #7	2018-11-29	56.775 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7019536

CarCheck.co.uk page 12/12