



report date: 2024-03-28

General information

Make	MINI
Model	MINI (R57) COOPER D
Colour	Orange
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-01-13
Pictures	43
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-01-30
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	22
Total items failed	7

MOT #16	2024-01-29 10:23
MOT test number	192092698381
Result	✓ Passed
Next expiry date	2025-01-30
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2023-01-23 14:43
MOT test number	259683861598
Result	✓ Passed

MOT #14	2022-01-31 13:54
MOT test number	653202156037
Result	✓ Passed

MOT #13	2022-01-31 13:54
MOT test number	999246845150
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #12** 2021-06-15 08:07**MOT test number** 295655479916**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-06-29 09:48**MOT test number** 842534835468**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2020-06-16 09:26**MOT test number** 328299565751**Result** ✗ Failed**Fail** Nearside Rear Service brake excessively fluctuating (1.2.1 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))**MOT #9** 2019-01-28 09:54**MOT test number** 988921286854**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre

**MOT #8** 2018-01-12 17:13**MOT test number** 969741173104**Result** ✓ Passed**MOT #7** 2017-02-02 13:08**MOT test number** 495906481174**Result** ✓ Passed**MOT #6** 2017-02-02 10:24**MOT test number** 229488857221**Result** ✗ Failed**Advice** Bulb warning lamp on**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside front tyre worn on edges**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #5** 2015-12-07 09:16**MOT test number** 709508952953**Result** ✓ Passed**Advice** Nail in nearside rear tyre**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-12-12 09:00**MOT test number** 496376244384**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2014-02-27 08:04
MOT test number	519308654010
Result	✓ Passed

MOT #2	2013-12-06 15:09
MOT test number	228470443301
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2013-12-06 13:25
MOT test number	477130143402
Result	✗ Failed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 February 2025

✓  
**MOT**

**Expires:**  
30 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	30 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-12-24
Last registration	2024-01-29
Complete history	<a href="#">See info</a>



Registration #1	2010-12-24	22 mi
Registration #2	2013-12-06	27.528 mi
Registration #3	2013-12-06	27.528 mi
Registration #4	2014-02-27	28.344 mi
Registration #5	2014-12-12	32.218 mi
Registration #6	2015-12-07	36.288 mi
Registration #7	2017-02-02	39.685 mi
Registration #8	2017-02-02	39.686 mi
Registration #9	2018-01-12	44.645 mi
Registration #10	2019-05-29	50.377 mi
Registration #11	2019-05-29	50.377 mi
Registration #12	2019-05-29	50.377 mi
Registration #13	2019-05-29	50.377 mi
Registration #14	2019-05-29	50.377 mi
Registration #15	2019-05-29	50.377 mi
Registration #16	2019-05-29	50.377 mi
Registration #17	2019-05-29	50.377 mi
Registration #18	2019-05-29	50.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1200 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats 4

<b>Number of axles</b>	2
<b>Engine number</b>	70077520