





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI HIGHLINE BLUEMOTION TECHNOLOGY
Colour	Blue
Year of manufacture	2016
Top speed	106 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-08-25

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

 Date
 2021-06-23

 Pictures
 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT	history
1.101	iliocol y

MOT expiry date	2024-06-21
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	16
Total items failed	0

MOT #8	2023-06-16 08:47
MOT test number	501014912940
Result	✓ Passed
Next expiry date	2024-06-21
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #7		2022-05-30 13:14
MOT test n	number	254860439214
Result		✓ Passed
MOT #6		2021-06-22 09:32
MOT test n	number	530989449346
Result		✓ Passed
MOT #5		2021-06-21 16:42
MOT test n	number	682648483779
Result		× Failed
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

MOT #4	2020-11-18 16:39
MOT test number	172935834152
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #3

GL66YBV

report date: 2024-03-29

2020-11-17 17:20

MOT test number

Result

Advice
(i))

Advice
(i)

Advice
(i)

Nearside Rear Outer Brake disc worn, but not excessively outer face of the disc is worn (1.1.14 (a)

Advice
(a) (i))

MAJOR Nearside Rear Service brake efficiency below requirements (1.2.2 (a) (i))

Advice Offside Front Outer Brake disc worn, but not excessively outer face of the disc is worn (1.1.14 (a) (i))

Advice Offside Front Outer Brake disc worn, but not excessively outer face of disc is worn (1.1.14 (a) (i))

MOT #2 2019-11-20 16:51

MOT test number 542953975430

Result \rightarrow Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2019-11-19 09:29

MOT test number 970562924190

Result ★ Failed

Minor Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

DANGEROUS Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

DANGEROUS Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/11



GL66YBV report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates. mber of plates. -

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



GL66YBV report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-12-31
Last registration	2023-06-16
Complete history	See info



Registration #1	2016-12-31	6 mi
Registration #2	2019-11-19	27.552 mi
Registration #3	2019-11-20	27.552 mi
Registration #4	2020-11-17	37.884 mi
Registration #5	2020-11-18	37.887 mi
Registration #6	2021-06-21	40.421 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 10/11



GL66YBV report date: 2024-03-29

Car features

50225	Air conditionir
50295	
60482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	***
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Wheel base	3 mm
Kerb weight	1594 kg
Max. allowed weight	2299 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
CarChock co.uk	pago 11/11

CarCheck.co.uk page 11/11

Number of seats	2
Number of axles	2
Engine number	DFSD084278