



report date: 2024-03-28

General information

Make	BMW
Model	525 525D M SPORT
Colour	Blue
Year of manufacture	2007
Top speed	147 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	400 Nm at 1.300 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-01
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-11
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	26
Total items failed	6

MOT #17	2023-06-21 14:47
MOT test number	756630205295
Result	✓ Passed
Next expiry date	2024-07-11

MOT #16	2022-06-25 09:26
MOT test number	170777651120
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2021-07-12 15:07
MOT test number	636817521740
Result	✓ Passed
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #14	2020-08-22 08:06
MOT test number	461827903734
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge tyre is worn on inner edge also perishing (5.2.3 (e))

**MOT #13** 2019-08-24 10:59**MOT test number** 239285709829**Result** ✓ Passed**MOT #12** 2018-08-06 12:32**MOT test number** 907745348894**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Vehicle under tray fitted**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-08-06 10:02**MOT test number** 971197686662**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Nearside Rear Nail in tyre**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Vehicle under tray fitted**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2017-08-15 16:20**MOT test number** 119763385087**Result** ✓ Passed



MOT #9	2016-08-16 16:07
MOT test number	393107249169
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #8	2015-08-17 17:26
MOT test number	585799525212
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7	2014-08-14 16:02
MOT test number	699526824276
Result	✓ Passed
Notice	Nail in offside front tyre
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #6	2014-08-14 15:20
MOT test number	107116024275
Result	✗ Failed
Notice	Nail in offside front tyre
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components
Fail	Offside Registration plate lamp not working (1.1.C.1d)

**MOT #5** 2013-08-25 17:13**MOT test number** 857017033246**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2012-12-20 14:31**MOT test number** 516865852394**Result** ✓ Passed**Notice** Oil level on min**MOT #3** 2012-12-19 15:33**MOT test number** 489034052328**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** Oil level on min**Advice** Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-12-21 11:29**MOT test number** 727395151367**Result** ✓ Passed**MOT #1** 2010-12-29 12:05**MOT test number** 823393660336**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
11 July 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	11 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-28
Last registration	2023-06-21
Complete history	See info



Registration #1	2007-11-28	8 mi
Registration #2	2010-12-29	34.536 mi
Registration #3	2011-12-21	43.076 mi
Registration #4	2012-12-19	53.033 mi
Registration #5	2012-12-20	53.033 mi
Registration #6	2013-08-25	56.381 mi
Registration #7	2014-08-14	60.907 mi
Registration #8	2014-08-14	60.907 mi
Registration #9	2015-08-17	65.373 mi
Registration #10	2016-08-16	69.823 mi
Registration #11	2016-08-16	69.823 mi
Registration #12	2016-08-16	69.823 mi
Registration #13	2016-08-16	69.823 mi
Registration #14	2016-08-16	69.823 mi
Registration #15	2016-08-16	69.823 mi
Registration #16	2016-08-16	69.823 mi
Registration #17	2016-08-16	69.823 mi
Registration #18	2016-08-16	69.823 mi
Registration #19	2016-08-16	69.823 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1655 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	25136552