



UK

SB6IMKV

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CRAFTER CR35 TDI H/R P/V
Colour	White
Year of manufacture	2012
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2021-05-21
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	21
Total items failed	6

MOT #9 2020-05-22 10:07

MOT test number 615242621069

Result ✓ Passed

Next expiry date 2021-05-21

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Integral body structure is deformed but structural rigidity is not significantly reduced (6.1.1 (a) (i))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))

MOT #8 2019-02-05 17:35

MOT test number 743943966294

Result ✓ Passed

**MOT #7** 2018-01-16 10:20**MOT test number** 958115349557**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Park brake effort only just met**Advice** Offside Rear Nail in tyre on inside**MOT #6** 2017-01-30 16:17**MOT test number** 697170052678**Result** ✓ Passed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Items removed from driver's view prior to test**MOT #5** 2017-01-30 16:17**MOT test number** 262832567966**Result** ✗ Failed**Pass with rectification** Front registration plate dirty (6.3.1d)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Items removed from driver's view prior to test**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**MOT #4** 2016-02-09 14:59**MOT test number** 186510544819**Result** ✓ Passed**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #3** 2016-02-05 10:57**MOT test number** 639385400798**Result** ✗ Failed**Fail** Nearside Headlamp aim too high (1.8)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Fail** Offside Headlamp aim too high and too far to the right. (1.8)**Fail** Offside Rear reflector missing (1.5.1a)**MOT #2** 2015-01-09 12:15**MOT test number** 397119205087**Result** ✓ Passed**Notice** Emissions too clean too test.**MOT #1** 2015-01-08 16:00**MOT test number** 237318505015**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Emissions too clean too test.



Tax & MOT check

✕
Untaxed

Tax expired:
24 January 2022

✕
MOT

Expired:
21 May 2021

Tax status	Expired at 24 January 2022
Days left	827 days too late
MOT expiry date	21 May 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SB61MKV
Plate since	2019-06-29
Current registration	 SB61MKV
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2012-01-31
Last registration	2020-05-22
Complete history	See info



Registration #1	2012-01-31	20 mi
Registration #2	2015-01-08	110.635 mi
Registration #3	2015-01-09	110.636 mi
Registration #4	2016-02-05	139.653 mi
Registration #5	2016-02-09	139.656 mi
Registration #6	2016-02-09	139.656 mi
Registration #7	2016-02-09	139.656 mi
Registration #8	2016-02-09	139.656 mi
Registration #9	2016-02-09	139.656 mi
Registration #10	2016-02-09	139.656 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	CKUC006865