



report date: 2024-03-29

General information

Make	MINI
Model	MINI ONE
Colour	Blue
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-02-02
Pictures	3
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-13
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	26
Total items failed	5

MOT #15 2024-02-10 10:37

MOT test number 620064405421

Result ✓ Passed

Next expiry date 2025-02-13

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Slight cracking on tread and sidewall (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Both front jacking blocks missing
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #14 2023-02-11 10:14

MOT test number 769693696379

Result ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both discs scored at outer faces (1.1.14 (a) (ii))

**MOT #13** 2022-02-09 14:02**MOT test number** 258782861810**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12** 2021-02-03 16:43**MOT test number** 376146740095**Result** ✓ Passed**MOT #11** 2021-01-28 09:18**MOT test number** 382800197778**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #10** 2020-02-14 12:06**MOT test number** 206985863692**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2020-02-14 12:06**MOT test number** 854332334681**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #8** 2019-02-12 16:27**MOT test number** 156928083488**Result** ✓ Passed**MOT #7** 2018-02-05 13:58**MOT test number** 931375447865**Result** ✓ Passed**MOT #6** 2017-01-10 13:50**MOT test number** 461417840476**Result** ✓ Passed**MOT #5** 2016-02-01 13:04**MOT test number** 771433625668**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-02-01 13:04**MOT test number** 883616735577**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-02-04 12:21**MOT test number** 145225635458**Result** ✓ Passed



MOT #2	2014-03-04 11:36
MOT test number	127123764036
Result	✓ Passed
Notice	Offside front outer egde worn close to limit
Notice	Nearside front tyre outer egde worn close to limit
Notice	Oil leak

MOT #1	2014-03-04 11:36
MOT test number	859823064065
Result	✗ Failed
Notice	Oil leak
Notice	Offside front outer egde worn close to limit
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Notice	Nearside front tyre outer egde worn close to limit



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
13 February 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	13 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-23
Last registration	2024-02-10
Complete history	See info



Registration #1	2011-03-23	18 mi
Registration #2	2014-03-04	24.029 mi
Registration #3	2015-02-04	30.620 mi
Registration #4	2016-02-01	46.125 mi
Registration #5	2016-02-01	46.125 mi
Registration #6	2017-01-10	56.032 mi
Registration #7	2018-02-05	62.411 mi
Registration #8	2019-02-12	69.785 mi
Registration #9	2020-02-12	75.277 mi
Registration #10	2020-02-12	75.277 mi
Registration #11	2020-02-12	75.277 mi
Registration #12	2020-02-12	75.277 mi
Registration #13	2020-02-12	75.277 mi
Registration #14	2020-02-12	75.277 mi
Registration #15	2020-02-12	75.277 mi
Registration #16	2020-02-12	75.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	B560J085