





General information

MakeBMWModelX3 XDRIVE20D SEColourBlueYear of manufacture2011Top speed130 mph0 - 60 mph8.5 seconds		
ColourBlueYear of manufacture2011Top speed130 mph0 - 60 mph8.5 seconds	Make	BMW
Year of manufacture 2011 Top speed 130 mph 0 - 60 mph 8.5 seconds	Model	X3 XDRIVE20D SE
Top speed 130 mph 0 - 60 mph 8.5 seconds	Colour	Blue
0 - 60 mph 8.5 seconds	Year of manufacture	2011
	Top speed	130 mph
	0 - 60 mph	8.5 seconds
Gearbox 6 speed Manual	Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	2.000 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F





MOT history

MOT expiry date	2025-01-29
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	31
Total items failed	5

MOT #17	2024-01-30 17:03
MOT test number	177582440589
Result	Passed
Next expiry date	2025-01-29
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Underneath tray fitted at the time of test	

MOT #16		2023-02-25 12:51
MOT test	number	572394259109
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Underneath tray fitted at the time of test	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #15	202	3-02-24 07:59	
MOT test numbe	ber 6	66576781653	
Result		🗙 Failed	
DANGEROUS required is 1.0mr		imum depth	
Advice Unde	lerneath tray fitted at the time of test		
Advice Offsic	ide Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
MAJOR Nears	rside Front Headlamp aim unable to be tested (4.1.2 (b))		
DANGEROUS Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))			
MAJOR Rear	r Registration plate lamp does not illuminate simultaneously with the position lam	ps (4.7.2 (a))	
Advice Nears	rside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
MAJOR Nears	rside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))		

MOT #14		2022-03-02 13:45
MOT test	number	999555602882
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Rear Registration plate deteriorated but not likely to be misread delaminating. (0.1 (b))		

MOT #13	2022-02-28 17:09
MOT test number	512265549382
Result	× Failed
Advice Rear Registration plate deteriorated but not likely to be misread delaminating. (0.1 (b))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
DANGEROUS Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))	





MOT #12		2021-03-11 07:57
MOT test	number	367528299876
Result		✓ Passed
Advice	Undertray not fully secure centre under trays damaged and insecure (8.1.1	(b) (i))
MOT #11		2021-03-10 15:46
MOT test	number	289655401604
Result		🗙 Failed
MAJOR	Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))	
Advice	Undertray not fully secure centre under trays damaged and insecure (8.1.1	(b) (i))
MAJOR	Offside Front Road wheel fixing missing (5.2.1 (a) (i))	
MAJOR	Offside Rear Road wheel fixing missing (5.2.1 (a) (i))	
MAJOR	Nearside Front Road wheel fixing missing (5.2.1 (a) (i))	

MOT #10	2020-03-03 09:53
MOT test number	493286134116
Result	✓ Passed

MOT #9	2019-02-13 13:54
MOT test number	209501239911
Result	✓ Passed

MOT #8	2018-03-07 12:08
MOT test number	444292491874
Result	✓ Passed

MOT #7	2017-03-11 09:20
MOT test number	564444554368
Result	✓ Passed





MOT #6	2016-12-13 10:57
MOT test number	743900108967
Result	🗙 Failed
Fail Offside Front Steering arm has relative movement at its fixings (2.2.B.	1h)
MOT #5	2016-01-15 11:20
MOT test number	830588200592
Result	✓ Passed
Advice Windscreen has damage to an area less than a 10mm circle within	zone 'A' (8.3.1a)
MOT #4	2016-01-15 11:20
MOT test number	400963818702
Result	🗙 Failed
Pass with rectification Nearside Headlamp aim too low (1.8)	
Advice Windscreen has damage to an area less than a 10mm circle within	zone 'A' (8.3.1a)

Pass with rectification Offside Headlamp aim too low (1.8)

МОТ #3	2015-01-08 12:04
MOT test number	576878505078
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #2		2014-02-03 09:36
MOT test	number	806494434031
Result		✓ Passed
Notice	Tyres 245/50/18 100h	
Notice	Front discs surface corrosion	





MOT #1		2014-02-03 09:36
MOT test number		878194334023
Result		🗙 Failed
Notice Tyres 245/50/18	100h	
Pass with rectification	Offside Headlamp aim too high (1.8)	
Notice Front discs surfa	ce corrosion	
Pass with rectification	Nearside Headlamp aim too high (1.8)	



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 29 January 2025
Tax status	Valid until 1 October
Days left	155
MOT expiry date	29 January 2025
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this BMW had different number plates	5.
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



GV60KHM report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-01-27
Last registration	2024-01-30
Complete history	See info



Registration #1	2011-01-27	22 mi
Registration #2	2014-02-03	37.173 mi
Registration #3	2015-01-08	50.187 mi
Registration #4	2016-01-15	62.890 mi
Registration #5	2016-01-15	62.890 mi
Registration #6	2016-12-13	70.107 mi
Registration #7	2017-03-11	70.112 mi
Registration #8	2018-03-07	71.786 mi
Registration #9	2019-02-13	79.608 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 mi
Registration #17		10.200 au





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1881 mm
Height	1675 mm
Length	4648 mm
Wheel base	2795 mm
Kerb weight	1715 kg
Max. allowed weight	2290 kg
Additional information	
Fuel tank capacity	67
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	71297600