



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 SPORT
Colour	White
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-09-14
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-13
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-03
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	27
Total items failed	2

MOT #15	2023-10-26 09:09
MOT test number	630825722067
Result	✓ Passed
Next expiry date	2024-11-03
Advice	Front radiator support corroded
Advice	Front Exhaust mounting defective (6.1.2 (a))

MOT #14	2023-10-25 10:32
MOT test number	852776960583
Result	✗ Failed
MAJOR	Offside Front Service brake excessively binding (1.2.1 (f))
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Front radiator support corroded
Advice	Front Exhaust mounting defective (6.1.2 (a))

**MOT #13** 2022-11-04 10:06**MOT test number** 516489856828**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12** 2022-10-26 09:32**MOT test number** 848526442669**Result** ✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Central Front Lower Items removed from driver's view prior to test
- Advice** Nearside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-10-25 12:34**MOT test number** 661372067172**Result** ✓ Passed

- Advice** Front radiator bracket corroded
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #10** 2020-11-26 11:20**MOT test number** 782654297833**Result** ✓ Passed

**MOT #9** 2019-11-22 09:11**MOT test number** 348915911922**Result** ✓ Passed**MOT #8** 2018-11-23 09:15**MOT test number** 577961747447**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement  
inner rear rubber bush soon require attention (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
inner rear rubber bush soon require attention (5.3.4 (a) (i))**MOT #7** 2017-11-27 09:25**MOT test number** 266602541693**Result** ✓ Passed**MOT #6** 2016-11-14 11:09**MOT test number** 529696947658**Result** ✓ Passed**MOT #5** 2015-11-28 09:54**MOT test number** 779474213734**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2014-12-01 12:57**MOT test number** 768545534322**Result** ✓ Passed**MOT #3** 2013-11-23 10:47**MOT test number** 345387723338**Result** ✓ Passed**MOT #2** 2013-11-22 10:23**MOT test number** 966046323380**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2012-11-22 16:09**MOT test number** 537577922380**Result** ✓ Passed**Notice** Under trays fitted



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
3 November 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	3 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-27
Last registration	2023-10-26
Complete history	<a href="#">See info</a>



Registration #1	2009-11-27	22 mi
Registration #2	2012-11-22	18.088 mi
Registration #3	2013-11-22	26.029 mi
Registration #4	2013-11-23	26.029 mi
Registration #5	2014-12-01	32.190 mi
Registration #6	2015-11-28	44.891 mi
Registration #7	2016-11-14	53.796 mi
Registration #8	2017-11-27	59.466 mi
Registration #9	2018-11-23	63.618 mi
Registration #10	2019-11-23	65.377 mi
Registration #11	2019-11-23	65.377 mi
Registration #12	2019-11-23	65.377 mi
Registration #13	2019-11-23	65.377 mi
Registration #14	2019-11-23	65.377 mi
Registration #15	2019-11-23	65.377 mi
Registration #16	2019-11-23	65.377 mi
Registration #17	2019-11-23	65.377 mi
Registration #18	2019-11-23	65.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number

156670