



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA SE PLUS TINO
Colour	Silver
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	158 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	36.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-16
Pictures	2
Listing price	View report



source: cargurus.co.uk

**MOT history****MOT #26** 2022-03-28 15:13**MOT test number** 832238957913**Result** ✗ Failed**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Build date (05/02) (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Lower Exhaust flexy joint worn**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Build date (47/07) (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing Build date (09/12) (5.2.3 (d) (ii))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge & outer (5.2.3 (e))**Advice** Central Front Lower Cross member, engine/gearbox & rad support area excessively corroded**MOT #25** 2021-07-01 15:54**MOT test number** 964739127349**Result** ✓ Passed**Advice** Plastic sill covers fitted at time of test**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside rear and offside front tyres worn on edges**MOT #24** 2020-07-13 10:55**MOT test number** 767348020814**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #23** 2020-07-13 10:55**MOT test number** 529581698962**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #22** 2019-06-26 11:50**MOT test number** 735885408477**Result** ✓ Passed**MOT #21** 2019-06-25 08:58**MOT test number** 979065441771**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))**Fail** Central Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #20** 2018-07-02 15:01**MOT test number** 815474419085**Result** ✓ Passed**Advice** Offside Front tyre perished in rain grooves**Advice** Front brake pads look low**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #19**

2018-07-02 09:34

MOT test number

699340510757

Result

✗ Failed

Advice Offside Front tyre perished in rain grooves**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Front brake pads look low**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**MOT #18**

2017-07-03 11:45

MOT test number

521505282404

Result

✓ Passed

Advice Plastic sill covers fitted at time of test**Advice** Front cross member starting to corrode**Advice** All four shock absorbers dust covers split**MOT #17**

2017-06-26 16:27

MOT test number

756749655019

Result

✗ Failed

Fail Nearside Rear Brake pipe excessively corroded by hose (3.6.B.2c)**Advice** Plastic sill covers fitted at time of test**Advice** All four shock absorbers dust covers split**Advice** Front cross member starting to corrode**MOT #16**

2016-06-16 14:20

MOT test number

107346186143

Result

✓ Passed

**MOT #15** 2015-07-06 16:14**MOT test number** 449447685104**Result** ✓ Passed**Notice** All four shock absorber dust covers split**Notice** Front cross member starting to corrode.**MOT #14** 2014-07-09 17:25**MOT test number** 198900494143**Result** ✓ Passed**MOT #13** 2014-07-09 12:56**MOT test number** 397070094117**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Emissions not tested (7.0)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #12** 2013-06-22 12:02**MOT test number** 728573273110**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Plastic sill covers fitted at time of test**Notice** Front crossmember corroded

**MOT #11** 2012-07-05 17:38**MOT test number** 279687682416**Result** ✓ Passed**Notice** Plastic sill covers fitted at time of test**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #10** 2012-06-25 12:17**MOT test number** 209777972488**Result** ✗ Failed**Notice** Offside front tyre on 2mm towards edges**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Emissions not tested (7.0)**Notice** Offside front tyre on 1.6mm towards edges and smooth on inner edge**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Plastic sill covers fitted at time of test**MOT #9** 2011-06-28 12:44**MOT test number** 135069771164**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #8** 2010-06-29 14:38**MOT test number** 151930080122**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #7** 2009-06-29 10:42**MOT test number** 221920989420**Result** ✓ Passed**Notice** Front brake pads look to be getting low**Notice** Offside and nearside front shock absorbers dust covers split**Notice** Plastic sill covers fitted at time of test**MOT #6** 2008-06-24 11:05**MOT test number** 393786978183**Result** ✓ Passed**Notice** Advise stone chip in front windscreen**MOT #5** 2008-06-24 09:29**MOT test number** 102356278143**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Advise stone chip in front windscreen**MOT #4** 2007-08-15 15:04**MOT test number** 873607027280**Result** ✓ Passed



MOT #3	2007-08-15 10:22
MOT test number	192797427217
Result	✗ Failed
Notice	Cut in n/s/f sidewall....front brake pads wearing low?....front tyres wearing low....
Fail	Rear registration plate character(s) likely to be misread (6.3.4b)
Fail	Offside Headlamp not working on dipped beam (1.7.5a)

MOT #2	2006-08-24 09:47
MOT test number	351306736451
Result	✓ Passed

MOT #1	2005-08-12 10:19
MOT test number	271434125267
Result	✓ Passed



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2002-09-01
Last registration	2022-03-28
Complete history	See info



Registration #1	2002-09-01	16 mi
Registration #2	2005-08-12	9.605 mi
Registration #3	2006-08-24	18.944 mi
Registration #4	2007-08-15	29.481 mi
Registration #5	2007-08-15	29.483 mi
Registration #6	2008-06-24	37.623 mi
Registration #7	2008-06-24	37.623 mi
Registration #8	2009-06-29	44.087 mi
Registration #9	2010-06-29	48.573 mi
Registration #10	2011-06-28	52.304 mi
Registration #11	2012-06-25	55.423 mi
Registration #12	2012-07-05	55.423 mi
Registration #13	2013-06-22	56.689 mi
Registration #14	2014-07-09	57.893 mi
Registration #15	2015-06-29	58.337 mi
Registration #16	2016-06-29	58.337 mi
Registration #17	2017-06-29	58.337 mi
Registration #18	2018-06-29	58.337 mi
Registration #19	2019-06-29	58.337 mi
Registration #20	2020-06-29	58.337 mi
Registration #21	2021-06-29	58.337 mi
Registration #22	2022-03-28	58.337 mi
Registration #23	2022-03-28	58.337 mi
Registration #24	2022-03-28	58.337 mi
Registration #25	2022-03-28	58.337 mi
Registration #26	2022-03-28	58.337 mi

Registration #27	2020-05-20	20,000,000
Registration #28	2020-05-20	20,000,000

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1420 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	176238