



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO 3100 SPORTIVE S/S L2H1 3100 SPORTIVE S/S DCB
Colour	Grey
Year of manufacture	2020
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	197 g/km
CO2 label	J






Internet history

Entry 4

Date	2022-01-07
Pictures	10
Listing price	View report



source: autoonline.co.uk



Entry 3

Date	2021-11-27
Pictures	0
Listing price	View report

source: heycar.co.uk


Entry 2

Date	2021-08-21
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 1

Date	2021-08-19
Pictures	26
Listing price	View report



source: cargurus.co.uk





MOT history

MOT expiry date	2024-06-29
MOT pass rate	50 %
MOT passed	1
Failed MOT tests	1
Total advice items	14
Total items failed	2

MOT #22023-06-23 14:06

MOT test number246751704871

Result✓ Passed

Next expiry date2024-06-29

- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Outer Nail in tyre screw in outer tread (Unrepairable)
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords Cuts in tread area (5.2.3 (d) (i))
- Advice** Rear Brake pad(s) wearing thin Rear brake pads worn low (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords cuts in tread area (5.2.3 (d) (i))
- Advice** Front Brake pad(s) wearing thin brake pads worn approx 90% (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))



MOT #12023-06-23 08:54

MOT test number906264214767

Result

Failed

- Fail

Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall cut / damaged (5.2.3 (d) (i))
- Advice

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords cuts in tread area (5.2.3 (d) (i))
- Advice

Rear Brake pad(s) wearing thin Rear brake pads worn low (1.1.13 (a) (ii))
- Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Offside Front Outer Nail in tyre screw in outer tread (Unrepairable)
- Fail

Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords multiple cuts in tread (5.2.3 (d) (i))
- Advice

Front Brake pad(s) wearing thin brake pads worn approx 90% (1.1.13 (a) (ii))
- Advice

Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Offside Front Tyre has a cut but not deep enough to reach the ply or cords Cuts in tread area (5.2.3 (d) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
29 June 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2020-06-30
Last registration	2023-06-23
Complete history	See info



Registration #1	2020-06-30	23 mi
Registration #2	2020-06-30	25,277 mi
Registration #3	2020-06-30	25,277 mi
Registration #4	2020-06-30	25,277 mi
Registration #5	2020-06-30	25,277 mi
Registration #6	2020-06-30	25,277 mi
Registration #7	2020-06-30	25,277 mi

More info >



Dimensions & weight

Width	2204 mm
Height	1935 mm
Length	5309 mm
Kerb weight	1770 kg
Max. allowed weight	2940 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	6
Number of seats	6
Engine number	10DY3M4025049 O4I