





report date: 2024-03-28

General information

| Make | PEUGEOT |
|---------------------|-------------------------|
| Model | 208 BLUE HDI ACCESS A/C |
| Colour | Grey |
| Year of manufacture | 2016 |
| Top speed | 106 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 75 BHP |
|-------------------------|---------------------|
| Max. torque | 230 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 67.3 mpg |
| Consumption extra urban | 94.2 mpg |
| Consumption combined | 80.7 mpg |
| CO2 emission | 90 g/km |
| CO2 label | A |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1


Date 2021-06-16

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-05-11 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 14 |
| Total items failed | 3 |

| MOT #6 | | 2023-05-11 14:35 |
|-----------|---|------------------|
| MOT test | number | 218732036606 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-05-11 |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #5 | 2023-05-10 13:55 |
|---|------------------|
| MOT test number | 509805501856 |
| Result | × Failed |
| Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail Driver's view of the road through the swept area of the windscreen significantly obstruction (3.1 (a) (ii)) | y affected by an |
| Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Fail Windscreen washer provides insufficient washer liquid (3.5 (a)) | |

CarCheck.co.uk page 3/11



report date: 2024-03-28

| MOT #4 | | 2022-05-12 06:46 |
|----------|--|------------------|
| MOT test | number | 358707081753 |
| Result | | ✓ Passed |
| | | |
| MOT #3 | | 2021-06-16 14:44 |
| MOT test | number | 270132249808 |
| Result | | ✓ Passed |
| | | |
| MOT #2 | | 2020-08-06 09:08 |
| MOT test | number | 873233732592 |
| Result | | ✓ Passed |
| Advice | Advice Items removed from driver's view prior to test | |
| Advice | Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Advice | Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Advice | Advice Nearside Rear Tyre slightly damaged uneven/stepped tread wear (5.2.3 (d) (ii)) | |

| MOT #1 | | 2019-08-13 14:52 |
|---|---|------------------|
| MOT test | number | 139874102698 |
| Result | | ✓ Passed |
| Advice | Nearside Front damage outer sidewall | |
| Advice Front Brake pad(s) wearing thin appear low (1.1.13 (a) (ii)) | | |
| Advice | Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 33 |
| MOT expiry date | 11 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
|---|-------------|
| | |
| manus . | |
| *************************************** | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | |
| Current registration | NK. |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-11-04 |
| Last registration | 2023-05-11 |
| Complete history | See info |



| Registration #1 | 2016-11-04 | 16 mi |
|-----------------|------------|-----------|
| Registration #2 | 2019-08-13 | 22.294 mi |
| Registration #3 | 2020-08-06 | 29.487 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 71.777 es |

More info >

page 10/11 CarCheck.co.uk



CU66OZD report date: 2024-03-28

Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 88% |
| Children | 78% |
| Pedestrian | 61% |
| Safety systems | 83% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1739 mm |
|---------------------|---------|
| Height | 1460 mm |
| Length | 3973 mm |
| Wheel base | 2538 mm |
| Kerb weight | 1075 kg |
| Max. allowed weight | 1635 kg |

Additional information

| Fuel tank capacity | 50 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/ |

Number of axles 2

Engine number JBHA0113588