





report date: 2024-03-29

General information

Make	VAUXHALL
Model	ADAM ENERGISED
Colour	Blue
Year of manufacture	2017
Top speed	102 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.229 сс
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	125 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-07-31

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-03-30
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	8
Total items failed	4

MOT #8		2024-03-25 15:39
MOT test	number	619195799811
Result		✓ Passed
Next expi	ry date	2025-03-30
Advice Tyre slightly damaged/cracking or perishing both rear tyres 215 45 17 (5.2.3 (d) (ii))		
Advice (5.2.3 (e))	Offside Front Tyre worn close to legal limit/worn on edge just above 3 m	nm centre tread 215 45 17

MOT #7	2024-03-25 11:31	
MOT test number	165755192355	
Result	X Failed	
Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))		
Advice Offside Front Tyre worn close to legal limit/worn on edge just above 3 mm centre tread 215 45 17 (5.2.3 (e))		
Advice Tyre slightly damaged/cracking or perishing both rear tyres 215 45 17 (5.3	2.3 (d) (ii))	

MOT #6	2023-03-27 14:56
MOT test number	183359755345
Result	✓ Passed
Advice Offside Front Shock absorbers has light misting of oil strut damp (5.3.2 (b))	

CarCheck.co.uk page 3/11



MOT #5 2023-03-27 11:25

MOT test number 558676159578

Result

X Failed

Fail Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure bulge in outer sidewall 215/45r17 (5.2.3 (d) (ii))

Advice

Offside Front Shock absorbers has light misting of oil strut damp (5.3.2 (b))

MOT #4 2022-03-30 09:59

MOT test number 799029748993

Result \(\sqrt{Passed} \)

Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #3 2021-03-09 18:07

MOT test number 710227744066

Result ✓ Passed

MOT #2 2021-03-09 18:07

MOT test number 694501221376

Result X Failed

Pass with rectification

Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Pass with rectification

Nearside Headlamp aim too low (4.1.2 (a))

MOT #1 2020-03-31 11:30

MOT test number 891513965746

Result ✓ Passed

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	30 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Damage 2

Date

Type

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	
NAME OF TAXABLE PARTY O	

99999999	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	IK NEW
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-03-21
Last registration	2024-03-25
Complete history	See info



Registration #1	2017-03-21	18 mi
Registration #2	2020-03-31	31.452 mi
Registration #3	2021-03-09	36.770 mi
Registration #4	2021-03-09	36.770 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1966 mm
Height	1483 mm
Length	3698 mm
Wheel base	2311 mm
Kerb weight	1011 kg
Max. allowed weight	1470 kg

Additional information

Fuel tank capacity	38 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	B12XER -19NN8638LWD

CarCheck.co.uk page 11/11