





report date: 2024-03-28

### General information

Make	AUDI
Model	A1 TDI S LINE
Colour	White
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/14



report date: 2024-03-28

## Internet history


### Entry 1

Date 2021-01-27

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

## MOT history

MOT expiry date	2025-04-05
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	23
Total items failed	11

MOT #17		2024-04-05 09:52
MOT test	number	750166162750
Result		✓ Passed
Next expi	ry date	2025-04-05
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))		

MOT #16		2024-04-03 08:18
MOT test	number	875317015018
Result		<b>×</b> Failed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))		
Fail Offside Rear Sub-frame attachment bracket/mounting missing bolt missing (5.3.3 (a) (ii))		

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT test number

Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

 MOT #14
 2022-01-25 12:24

 MOT test number
 131768034216

 Result
 ✓ Passed

MOT #13

MOT test number

Result

Fail Nearside Front Direction indicator incorrect colour (4.4.3 (a))

Fail Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT test number

Result

Advice (a) (ii))

Possed 2021-01-21 11:15

Advice (a) (iii)

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #11 2021-01-20 15:11

**MOT test number** 766259080863

**Result** X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

Fail
Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

**MOT #10** 2020-08-29 11:42

**MOT test number** 410645017253

Result \rightarrow Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2019-09-21 12:17

MOT test number 895361046576

**Result** ✓ Passed

MOT #8 2019-09-21 12:17

**MOT test number** 894154450495

Result × Failed

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Pass with rectification Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #7 2018-09-15 10:20

**MOT test number** 605403666257

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #6 2017-09-25 10:36 **MOT test number** 719802127841 Result ✓ Passed MOT #5 2016-11-23 17:39 **MOT** test number 780577065139 Result ✓ Passed **Advice** Offside Front worn on inner edge Advice Nearside Front worn on inner edge Front Brake pad(s) wearing thin (3.5.1g) Advice

MOT test number

S11829041861

Result

Advice Offside Front worn on inner edge

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front worn on inner edge


Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #3	2015-11-26 08:39
MOT test number	664143199333
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28



MOT #1		2013-10-17 10:35
MOT test	number	355550893450
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

CarCheck.co.uk page 7/14



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	5 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

### Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a> .		
THE STATE OF THE S		
***************************************		
***************************************		
*********		
***************************************		
***************************************		
	More info >	
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	NK SIN	
Plate since		
	More info >	

CarCheck.co.uk page 11/14



report date: 2024-03-28

### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-11-26
Last registration	2024-04-05
Complete history	See info



2010-11-26	6 mi
2013-10-17	19.125 mi
2014-10-15	21.507 mi
2015-11-26	32.669 mi
2016-11-23	43.711 mi
2016-11-23	43.711 mi
2017-09-25	56.969 mi
2018-09-15	73.178 mi
2019-09-21	88.957 mi
2019-09-21	88.957 mi
	11.777 es
	91.777 es
	11.777 es
	11.777 es
	D.777 es
	11.777 mg
	2013-10-17 2014-10-15 2015-11-26 2016-11-23 2016-11-23 2017-09-25 2018-09-15 2019-09-21

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

### Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	90%
Children	79%
Pedestrian	49%
Safety systems	86%
Overall rating	79%
Video	see crash video



## Dimensions & weight

Width	1740 mm
Height	1416 mm
Length	3954 mm
Wheel base	2469 mm
Kerb weight	1140 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 14/14

**Engine number** 

CAY980229