





report date: 2024-03-28

### General information

Make	FIAT
Model	GRANDE PUNTO T-JET SPORTING
Colour	Black
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	118 BHP
Max. torque	206 Nm at 1.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg



CarCheck.co.uk page 1/13



OV58TYG
report date: 2024-03-28

## Internet history

Entry 1
---------

Life y 1	
Date	2022-02-24
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



OV58TYG
report date: 2024-03-28

2021-09-22 10:28

MOT history

**MOT #14** 

MOT test number	690868309746
Result	✓ Passed
Next expiry date	2022-09-21

Advice Nearside Front Inner Play in steering rack inner joint(s)

Advice Central Front Exhaust has a minor leak of exhaust gases joint where cat meets the turbo has blow (6.1.2 (a))

**Advice** Offside Front Inner Play in steering rack inner joint(s)

Advice Offside Front Lower Steering column universal joint has slight wear or play bottom u/j (2.2.2 (c))

MOT #13	2021-08-16 13:39
MOT test number	826055114161
Result	<b>X</b> Failed
MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))	

**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MAJOR** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MAJOR Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2

(a))

**MAJOR** Central Exhaust system insecure (6.1.2 (a))

MOT #12	2020-09-08 16:24
MOT test number	513549770438

**Advice** Rear exhaust box corroding

**Advice** Stone chip in front screen

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #11

MOT test number

Result

Advice Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #10

MOT test number

Result

Advice Offside Rear Nail in tyre

2018-09-12 13:47

366847212139

✓ Passed

MOT test number

Result

Advice Rear brake discs corroded

Advice Undertrays fitted

Advice No oil on dipstick

Advice Exhaust corroded

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #8 2017-09-01 09:05 **MOT test number** 505155757361 Result **★** Failed **Advice** Nearside Front tyre bald inner edge Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a) Advice Front brake discs heavily corroded **Advice** Exhaust corroded Fail Front Brakes imbalanced across an axle (3.7.B.5b) No oil on dipstick Advice Advice Rear brake discs corroded Advice Undertrays fitted

MOT #7	2016-09-14 11:03
MOT test number	795748771746
Result	✓ Passed
	2016 00 07 10 00
MOT took mumber	2016-09-07 10:08
MOT test number  Result	774072169089 <b>X</b> Failed
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	₹ l'alleu

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #5	2	015-08-22 10:01
MOT test	number	107374635242
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Low on engine oil	
Notice	Under-trays fitted obscuring some underside components	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Nail in nearside rear tyre	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1	i)

MOT #4	20	14-09-09 12:12
MOT test	number	456692754260
Result		✓ Passed
Notice	Rear silencer corroded	
Advice	Vice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Under-trays fitted obscuring some underside components	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #3	2013-08-24 15:29
MOT test number	705416733248
Result	✓ Passed
MOT #2	2012-08-28 17:13
MOT test number	319681142218
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT #1 2011-09-13 11:02 MOT test number 805166651291

**Result** ✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

0	و من مطما ما
Owner	nistory

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		2?
***************************************		
***************************************		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		,
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NIE NIE UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-12-01
Last registration	2021-09-22
Complete history	See info



Registration #1	2008-12-01	28 mi
Registration #2	2011-09-13	27.827 mi
Registration #3	2012-08-28	34.147 mi
Registration #4	2013-08-24	40.613 mi
Registration #5	2014-09-09	48.337 mi
Registration #6	2015-08-22	45.920 mi
Registration #7	2016-09-07	62.097 mi
Registration #8	2016-09-14	62.181 mi
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.777 au

More info >

page 12/13 CarCheck.co.uk



report date: 2024-03-28

## Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1715 kg

### Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13

Number of axles2Engine number1221575