



RENAULT

**YS53EZH**

report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE DCI 120
Colour	Silver
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	270 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg





Internet history

Entry 1

Date	2021-02-04
Pictures	2
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history****MOT #15** 2015-07-23 14:18**MOT test number** 329144305490**Result** ✓ Passed**Next expiry date** 2016-07-30

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Play in steering rack inner joint(s)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #14** 2014-07-31 17:09**MOT test number** 336032014444**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Front strut mounts/bearings noisy
- Notice** Offside front coil spring corroded
- Notice** Under-trays fitted obscuring some underside components
- Notice** Play in steering rack inner joint(s)
- Notice** Horn not very loud

**MOT #13**

2014-07-31 14:58

**MOT test number**

446632514276

**Result****✗ Failed**

- Notice** Under-trays fitted obscuring some underside components
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Notice** Play in steering rack inner joint(s)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Notice** Rear brake discs worn and got hot
- Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Notice** Offside front coil spring corroded
- Fail** Front registration plate deteriorated (6.3.1d)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Notice** Front strut mounts/bearings noisy
- Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Notice** Horn not very loud
- Fail** Rear An item not tested (Manual)

**MOT #12**

2013-07-30 14:32

**MOT test number**

516061313291

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2013-07-29 15:59**MOT test number** 845300613222**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Fail** Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #10** 2011-11-30 11:47**MOT test number** 239234031300**Result** ✓ Passed**MOT #9** 2011-11-30 11:47**MOT test number** 427454231361**Result** ✗ Failed**Pass with rectification** Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**MOT #8** 2010-11-12 12:41**MOT test number** 883476410300**Result** ✓ Passed**MOT #7** 2010-02-03 11:54**MOT test number** 103734430070**Result** ✓ Passed

**MOT #6** 2010-02-03 10:41**MOT test number** 982454430029**Result** ✗ Failed

- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

**MOT #5** 2009-02-10 15:28**MOT test number** 132711549434**Result** ✓ Passed

- Advice** Offside Rear brake disc slightly pitted (3.5.1h)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear brake disc slightly pitted (3.5.1h)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2009-01-26 15:29**MOT test number** 804016129098**Result** ✗ Failed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Outer Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)
- Advice** Nearside Rear brake disc slightly pitted (3.5.1h)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear brake disc slightly pitted (3.5.1h)

**MOT #3** 2008-02-01 16:44**MOT test number** 150292838095**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Outer Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2008-02-01 14:32**MOT test number** 330992838034**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Outer Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2006-12-04 09:58**MOT test number** 820638836345**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>YS53EZH</b>
Plate since	2019-03-29
Current registration	<b>YS53EZH</b>
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2003-11-17
Last registration	2015-07-23
Complete history	<a href="#">See info</a>



Registration #1	2003-11-17	15 mi
Registration #2	2006-12-04	30.847 mi
Registration #3	2008-02-01	38.655 mi
Registration #4	2008-02-01	38.656 mi
Registration #5	2009-01-26	44.309 mi
Registration #6	2009-02-10	44.508 mi
Registration #7	2010-02-03	50.060 mi
Registration #8	2010-02-03	50.062 mi
Registration #9	2010-02-03	50.062 mi
Registration #10	2010-02-03	50.062 mi
Registration #11	2010-02-03	50.062 mi
Registration #12	2010-02-03	50.062 mi
Registration #13	2010-02-03	50.062 mi
Registration #14	2010-02-03	50.062 mi
Registration #15	2010-02-03	50.062 mi
Registration #16	2010-02-03	50.062 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Kerb weight	1270 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	C105777