



HONDA



report date: 2024-03-29

General information

Make	HONDA
Model	JAZZ I-VTEC EX
Colour	Grey
Year of manufacture	2017
Top speed	113 mph
0 - 60 mph	12.3 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	101 BHP
Max. torque	123 Nm at 5.000 rpm
Engine capacity	1.318 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	C







## Internet history

### Entry 3

Date	2021-11-04
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date	2021-11-03
Pictures	22
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-09-21
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #5	2023-09-18 12:40
MOT test number	775151312163
Result	✓ Passed
Next expiry date	2024-09-21

MOT #4	2022-09-12 09:11
MOT test number	261374578175
Result	✓ Passed

MOT #3	2021-09-22 09:23
MOT test number	619835703327
Result	✓ Passed

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing perished inside tread pattern,,,also 3,5mm tread,, (5.2.3 (d) (ii))

**Advice** Engine cover under car,.

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tyre perished inside tread pattern,,,advise keep check,. (5.2.3 (d) (ii))

MOT #2	2020-09-17 07:43
MOT test number	153483093774
Result	✓ Passed

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing damage on outer sidewall (5.2.3 (d) (ii))

**Advice** Offside Rear Brake disc worn, but not excessively disc red in colour ( overheating (1.1.14 (a) (i))



MOT #1	2020-09-15 14:38
MOT test number	794717714245
Result	✗ Failed
Advice	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Offside Rear Brake disc worn, but not excessively disc red in colour ( overheating (1.1.14 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened disc corroded on outer surface (1.1.14 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing damage on outer sidewall (5.2.3 (d) (ii))
DANGEROUS	Offside Rear Brake pad(s) less than 1.5 mm thick outer pad (1.1.13 (a) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
21 September 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	21 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	<b>SG67VTO</b>
Plate since	2019-03-29
Current registration	<b>SG67VTO</b>
Plate since	2019-03-29

More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-14
Last registration	2023-09-18
Complete history	<a href="#">See info</a>



Registration #1	2017-09-14	28 mi
Registration #2	2020-09-15	15.770 mi
Registration #3	2020-09-17	15.774 mi
Registration #4	2020-09-20	15.777 mi
Registration #5	2021-09-22	16.537 mi
Registration #6	2022-09-24	16.537 mi
Registration #7	2022-09-26	16.537 mi
Registration #8	2022-09-28	16.537 mi
Registration #9	2023-09-18	16.537 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	85%
Pedestrian	73%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1694 mm
Height	1550 mm
Length	3995 mm
Wheel base	2530 mm
Kerb weight	1132 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L13B21160060