



Mercedes-Benz

SP53LVU

report date: 2024-03-28

General information

Make	MERCEDES
Model	CL 500 CL500
Colour	Silver
Year of manufacture	2003
Top speed	155 mph
0 - 60 mph	6.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	302 BHP
Max. torque	460 Nm at 2.700 rpm
Engine capacity	4.966 cc
Cylinders	8
Fuel type	Petrol
Consumption city	14.6 mpg
Consumption extra urban	28.5 mpg
Consumption combined	21.1 mpg
CO2 emission	299 g/km
CO2 label	M







Internet history

Entry 1

Date	2022-05-12
Pictures	46
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-17
MOT pass rate	94 %
MOT passed	17
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #18	2024-01-09 10:58
MOT test number	754657079491
Result	✓ Passed
Next expiry date	2025-01-17

MOT #17	2022-12-20 15:37
MOT test number	876645787514
Result	✓ Passed

MOT #16	2022-01-18 10:30
MOT test number	331862533532
Result	✓ Passed

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #15	2020-06-09 14:31
MOT test number	959079010075
Result	✓ Passed

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2019-03-04 14:38

MOT test number

183453663654

Result

✓ Passed

- Advice** Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13

2018-02-20 08:54

MOT test number

140665708856

Result

✓ Passed

- Advice** Nearside Rear Brake pipe slightly corroded main pipe to rear (3.6.B.2c)
- Advice** Offside Rear Brake pipe slightly corroded main pipe to rear (3.6.B.2c)

MOT #12

2017-02-08 14:37

MOT test number

346061516268

Result

✓ Passed

MOT #11

2015-11-05 11:17

MOT test number

376890344659

Result

✓ Passed

**MOT #10** 2014-11-17 16:15**MOT test number** 876731424327**Result** ✓ Passed**MOT #9** 2013-11-18 14:28**MOT test number** 516902023367**Result** ✓ Passed**MOT #8** 2012-11-26 09:07**MOT test number** 479491632447**Result** ✓ Passed**MOT #7** 2011-12-20 14:08**MOT test number** 897614351336**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2010-09-15 10:32**MOT test number** 480388950278**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2010-02-27 10:23**MOT test number** 301048850074**Result** ✓ Passed**MOT #4** 2008-08-13 13:28**MOT test number** 814276028299**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)



MOT #3	2008-08-13 13:28
MOT test number	940356828285
Result	✓ Passed
MOT #2	2007-08-30 10:56
MOT test number	510762247275
Result	✓ Passed
MOT #1	2006-09-13 12:05
MOT test number	852186856272
Result	✓ Passed
Advice	Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 January 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 SP53LVU
Plate since	2019-06-29
Current registration	 SP53LVU
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2003-09-01
Last registration	2024-01-09
Complete history	See info



Registration #1	2003-09-01	23 mi
Registration #2	2006-09-13	10.149 mi
Registration #3	2007-08-30	12.369 mi
Registration #4	2008-08-13	19.243 mi
Registration #5	2010-02-27	30.105 mi
Registration #6	2010-09-15	31.320 mi
Registration #7	2011-12-20	47.962 mi
Registration #8	2012-11-26	53.909 mi
Registration #9	2013-11-18	56.055 mi
Registration #10	2014-11-17	59.032 mi
Registration #11	2015-05-20	59.377 mi
Registration #12	2016-05-20	59.377 mi
Registration #13	2017-05-20	59.377 mi
Registration #14	2018-05-20	59.377 mi
Registration #15	2019-05-20	59.377 mi
Registration #16	2020-05-20	59.377 mi
Registration #17	2021-05-20	59.377 mi
Registration #18	2022-05-20	59.377 mi
Registration #19	2023-05-20	59.377 mi

More info >



Dimensions & weight

Width	1854 mm
Height	1397 mm
Length	5003 mm
Wheel base	2885 mm
Kerb weight	1790 kg

Additional information

Fuel tank capacity	88 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11396030507739