




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Grey
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 3

Date 2022-02-19

Pictures 3

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date 2021-09-06

Pictures 13

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date 2021-06-29

Pictures 14

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-31
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #13	2023-06-01 08:44
MOT test number	778284187691
Result	✓ Passed
Next expiry date	2024-05-31

MOT #12	2022-05-24 11:29
MOT test number	173588196918
Result	✓ Passed

MOT #11	2021-05-24 13:06
MOT test number	227530549315
Result	✓ Passed

**MOT #10**

2020-06-01 12:00

MOT test number

372867864052

Result

✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Road wheel slightly distorted badly distorted on inner rim (5.2.2 (c) (i))

MOT #9

2019-03-25 10:37

MOT test number

328417269383

Result

✓ Passed

- Advice** Offside front tyre bold on inner edge

MOT #8

2018-04-14 12:03

MOT test number

793160904076

Result

✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Under tray fitted.

MOT #7

2018-04-14 12:03

MOT test number

978729361725

Result

✗ Failed

- Advice** Under tray fitted.
- Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Child Seat fitted not allowing full inspection of adult belt



MOT #6	2017-04-13 13:59
---------------	------------------

MOT test number	185727527929
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2016-10-14 12:27
---------------	------------------

MOT test number	387401301816
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2016-04-14 14:49
---------------	------------------

MOT test number	506470083247
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2015-10-21 12:15
---------------	------------------

MOT test number	504724918789
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2015-09-07 15:10
---------------	------------------

MOT test number	629347086771
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2015-09-07 13:11
---------------	------------------

MOT test number	516872274116
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Offside Rear coil spring broken (2.4.C.1a)
-------------	--



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
31 May 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 OV62AEG
Plate since	2019-03-29
Current registration	 OV62AEG
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-09-28
Last registration	2023-06-01
Complete history	See info



Registration #1	2012-09-28	25 mi
Registration #2	2015-09-07	23.427 mi
Registration #3	2015-09-07	23.427 mi
Registration #4	2015-10-21	24.195 mi
Registration #5	2016-04-14	29.012 mi
Registration #6	2016-10-14	34.626 mi
Registration #7	2017-04-13	40.015 mi
Registration #8	2018-04-14	60.029 mi
Registration #9	2018-04-14	60.029 mi
Registration #10	2019-04-14	60.029 mi
Registration #11	2019-04-14	60.029 mi
Registration #12	2019-04-14	60.029 mi
Registration #13	2019-04-14	60.029 mi
Registration #14	2019-04-14	60.029 mi
Registration #15	2019-04-14	60.029 mi
Registration #16	2019-04-14	60.029 mi
Registration #17	2019-04-14	60.029 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1474 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

CAYCK90899