



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Black
Year of manufacture	2007
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2


Date	2021-09-02
Pictures	25
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-01
Pictures	25
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-29
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	27
Total items failed	9

MOT #20	2023-09-30 12:46
MOT test number	528828594724
Result	✓ Passed
Next expiry date	2024-09-29
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #19	2023-09-29 09:10
MOT test number	100631117275
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
Fail	Offside Front Direction indicator incorrect colour (4.4.3 (a))
Fail	Offside Front Subframe mounting prescribed area excessively damaged significantly reducing structural strength subframe damaged (5.3.6 (a) (i))

**MOT #18**

2022-09-24 14:41

MOT test number

968072347378

Result

✓ Passed

Advice

Front Headlamp has a product on the lens but not seriously reducing light output cloudy (4.1.4 (b))

Advice

Rear exhaust box corroded

MOT #17

2021-09-24 15:50

MOT test number

345220713188

Result

✓ Passed

Advice

Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice

Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2020-09-11 13:15

MOT test number

967431293868

Result

✓ Passed

Minor

Nearside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement Console bush cracked (5.3.4 (a) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor

Offside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Front Headlamp has a product on the lens but not seriously reducing light output Clouded (4.1.4 (b))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened Lipped but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement Console bush cracked (5.3.4 (a) (i))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2019-09-12 10:49**MOT test number** 964922293994**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #14** 2019-09-11 16:02**MOT test number** 559409107525**Result** ✗ Failed**Advice** Vehicles internal headlight adjuster altered to recheck lights**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #13** 2018-09-13 10:29**MOT test number** 842060488934**Result** ✓ Passed**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**MOT #12** 2018-09-12 12:13**MOT test number** 525129134523**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**MOT #11** 2017-09-13 10:04**MOT test number** 890636399153**Result** ✓ Passed

**MOT #10** 2016-09-14 14:09**MOT test number** 685884956650**Result** ✓ Passed**MOT #9** 2015-09-10 09:26**MOT test number** 192618747878**Result** ✓ Passed**MOT #8** 2014-09-10 16:50**MOT test number** 109273254230**Result** ✓ Passed**MOT #7** 2014-09-10 16:50**MOT test number** 119683054214**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2013-09-12 12:58**MOT test number** 687285053240**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-09-12 12:58**MOT test number** 907255353249**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Brake servo vacuum pipe split (3.6.C.1b)

**MOT #4** 2012-09-10 14:17**MOT test number** 119624852224**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3 2012-09-10 14:17**MOT test number** 427554752218**Result** ✗ Failed

Pass with rectification Nearside Headlamp aim too high (1.8)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2 2011-09-26 10:57**MOT test number** 908409661232**Result** ✓ Passed**MOT #1** 2010-09-22 13:15**MOT test number** 631075960274**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
23 April 2024

✓

MOT

Expires:
29 September 2024

Tax status	Expired at 23 April 2024
Days left	6 days too late
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-28
Last registration	2023-09-30
Complete history	See info



Registration #1	2007-09-28	26 mi
Registration #2	2010-09-22	12.252 mi
Registration #3	2011-09-26	16.550 mi
Registration #4	2012-09-10	20.693 mi
Registration #5	2013-09-12	25.056 mi
Registration #6	2014-09-10	29.586 mi
Registration #7	2015-09-10	34.299 mi
Registration #8	2016-09-14	39.878 mi
Registration #9	2017-09-13	45.148 mi
Registration #10	2018-09-12	49.688 mi
Registration #11	2019-09-20	54.377 mi
Registration #12	2020-09-20	59.117 mi
Registration #13	2021-09-20	63.917 mi
Registration #14	2022-09-20	68.777 mi
Registration #15	2023-09-20	73.697 mi
Registration #16	2024-09-20	78.677 mi
Registration #17	2025-09-20	83.717 mi
Registration #18	2026-09-20	88.817 mi
Registration #19	2027-09-20	93.977 mi
Registration #20	2028-09-20	99.197 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 375475