





report date: 2024-03-28

General information

Make	AUDI
Model	A1 TDI S LINE
Colour	Grey
Year of manufacture	2015
Top speed	124 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 3.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	91.1 mpg
Consumption combined	80.7 mpg
CO2 emission	97 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-07-28	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-03
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	21
Total items failed	5

MOT #8	2023-06-29 15:27
MOT test number	774978519670
Result	✓ Passed
Next expiry date	2024-07-03

MOT #7	2023-06-26 11:04
MOT test number	589592447074
Result	X Failed
Fail Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))	

MOT #6	2022-07-04 08:43
MOT test number	616336839128
Result	✓ Passed
Advice Items removed from driver's view prior to test	

MOT #5		2021-06-24 15:37
MOT test r	number	449545433869
Result		✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #4 2020-07-03 14:07

MOT test number 129196595168

number	129196595168
	✓ Passed
Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 ($lpha$	a) (ii))
Nearside Rear Tyre slightly damaged/cracking or perishing 2253518 (5.2.3 (d) (ii))	
Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Rear Brake pad(s) wearing thin rear pads appear low advise more detailed inspection	n (1.1.13 (a)
Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Offside Rear Tyre slightly damaged/cracking or perishing 2253518 (5.2.3 (d) (ii))	
	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a Nearside Rear Tyre slightly damaged/cracking or perishing 2253518 (5.2.3 (d) (ii)) Nearside Rear Child Seat fitted not allowing full inspection of adult belt Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 Rear Brake pad(s) wearing thin rear pads appear low advise more detailed inspection Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2020-07-03 10:39 640349367404

Result X Failed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake pad(s) wearing thin rear pads appear low advise more detailed inspection (1.1.13 (a) (ii))

Fail Nearside Front Tyre has ply or cords exposed 2253518 (5.2.3 (d) (ii))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 2253518 (5.2.3 (d) (ii))

Fail Front Undertray likely to become detached (6.2.1 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Fail Offside Front Tyre has ply or cords exposed 2253518 (5.2.3 (d) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Tyre slightly damaged/cracking or perishing 2253518 (5.2.3 (d) (ii))

Advice Tpms light on system working

MOT #2 2019-05-01 08:48

MOT test number 999253985515

Result

Passed

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #1 2018-05-05 10:44

MOT test number 944192944529

Result

Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	3 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	

Plate changes	More info >
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	SIE UK
Plate since	
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

 $\quad \text{More info} \quad > \quad$


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-01
Last registration	2023-06-29
Complete history	See info



Registration #1	2015-05-01	27 mi
Registration #2	2018-05-05	42.840 mi
Registration #3	2019-05-01	52.920 mi
Registration #4	2020-07-03	69.587 mi
Registration #5	2020-07-03	69.587 mi
_		
Registration #6		71,777 es
Registration #6 Registration #7		11.777 ea
-		1.77 m
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 11/12





Car features

50225	Air conditioni
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	79%
Pedestrian	49%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1740 mm
Height	1416 mm
Length	3973 mm
Wheel base	2469 mm
Kerb weight	1150 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number CXMA021446