



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT TDI CC
Colour	Black
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G





## Internet history

### Entry 3

Date	2021-08-28
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date	2021-07-30
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date	2021-06-16
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-02-02
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	19
Total items failed	1

MOT #15	2024-02-03 11:58
MOT test number	896891354311
Result	✓ Passed
Next expiry date	2025-02-02

MOT #14	2024-02-03 11:58
MOT test number	683954046728
Result	✗ Failed
<b>Pass with rectification</b> Front Position lamp not working (4.2.1 (a) (ii))	

MOT #13	2023-02-10 13:49
MOT test number	269888415342
Result	✓ Passed

MOT #12	2022-02-12 14:34
MOT test number	872009106296
Result	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))
<b>Advice</b>	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #11** 2021-02-15 14:25**MOT test number** 270135294681**Result** ✓ Passed**MOT #10** 2020-02-19 15:53**MOT test number** 672625897086**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #9** 2020-02-19 14:48**MOT test number** 559749154407**Result** ✗ Failed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2019-03-09 11:04**MOT test number** 296246492589**Result** ✓ Passed**MOT #7** 2018-05-15 11:16**MOT test number** 394037399054**Result** ✓ Passed**MOT #6** 2017-07-19 09:21**MOT test number** 941601350300**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened rusty (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened rusty (3.5.1i)

**MOT #5** 2016-07-18 08:13**MOT test number** 594760905102**Result** ✓ Passed**Advice** Rear tyres stepping on insides**MOT #4** 2015-07-09 09:19**MOT test number** 775170195170**Result** ✓ Passed**MOT #3** 2014-07-14 10:25**MOT test number** 669295894112**Result** ✓ Passed**MOT #2** 2013-07-15 13:10**MOT test number** 115536393190**Result** ✓ Passed**Notice** Nearside front and spare tyre are "y" rated, the other three are "w" rated**Notice** Under-trays fitted obscuring some underside components**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Notice** Offside front tyre worn to 3mm in places**Notice** Nearside front tyre is not extra load**Notice** Nearside rear tyre feathered on inner edge**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Both rear tyres worn to 2mm in places**Notice** Spare tyre worn to 0mm in places



MOT #1	2012-07-19 10:54
MOT test number	307451102205
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
2 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	2 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>WL09LPV</b>
Plate since	2019-09-29
Current registration	<b>WL09LPV</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-08-05
Last registration	2024-02-03
Complete history	<a href="#">See info</a>



Registration #1	2009-08-05	29 mi
Registration #2	2012-07-19	24.719 mi
Registration #3	2013-07-15	36.536 mi
Registration #4	2014-07-14	49.065 mi
Registration #5	2015-07-09	62.138 mi
Registration #6	2016-07-18	74.126 mi
Registration #7	2017-07-19	85.147 mi
Registration #8	2018-05-15	94.389 mi
Registration #9	2019-03-09	98.263 mi
Registration #10	2020-02-19	109.964 mi
Registration #11	2020-05-20	111.277 mi
Registration #12	2020-05-20	111.277 mi
Registration #13	2020-05-20	111.277 mi
Registration #14	2020-05-20	111.277 mi
Registration #15	2020-05-20	111.277 mi
Registration #16	2020-05-20	111.277 mi
Registration #17	2020-05-20	111.277 mi
Registration #18	2020-05-20	111.277 mi
Registration #19	2020-05-20	111.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1417 mm
Length	4799 mm
Wheel base	2708 mm
Kerb weight	1466 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	4
Number of axles	2
Engine number	CBA 122280