



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 S S40
Colour	Gold
Year of manufacture	2008
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history


Entry 1

Date	2021-07-10
Pictures	1
Listing price	View report

AA

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-07-18
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	29
Total items failed	3

MOT #16 2023-07-07 11:32**MOT test number** 531044921393**Result** Passed**Next expiry date** 2024-07-18**Advice** Rear suspension & arms corrosion**Advice** Both front struts corrosion**Advice** Rear axle flexi hoses corrosion**MOT #15** 2022-07-19 11:20**MOT test number** 788035861295**Result** Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #14** 2022-07-19 11:20**MOT test number** 217909509680**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #13 2021-07-07 08:53**MOT test number** 212850487278**Result** ✓ Passed**MOT #12** 2020-08-29 08:11**MOT test number** 524700729196**Result** ✓ Passed**MOT #11** 2019-09-25 11:04**MOT test number** 985547712732**Result** ✓ Passed**MOT #10** 2018-09-19 15:21**MOT test number** 611183156921**Result** ✓ Passed

**MOT #9** 2018-09-18 13:23**MOT test number** 843211648076**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2017-09-19 08:28**MOT test number** 217286475268**Result** ✓ Passed**MOT #7** 2016-09-24 10:06**MOT test number** 132395358083**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm has slight play in a ball joint rearmost bush (2.4.G.2)**Advice** Oil leak**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush rearmost bush (2.4.G.2)**Advice** Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)**MOT #6** 2015-09-28 09:09**MOT test number** 546614169806**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-09-28 09:09**MOT test number** 339987139691**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-09-20 08:31**MOT test number** 929913764228**Result** ✓ Passed**MOT #3** 2013-08-29 11:44**MOT test number** 455981343219**Result** ✓ Passed**MOT #2** 2012-08-30 16:12**MOT test number** 377763842452**Result** ✓ Passed**MOT #1** 2011-09-05 12:23**MOT test number** 557628941229**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
18 July 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	18 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-28
Last registration	2023-07-07
Complete history	See info



Registration #1	2008-09-28	11 mi
Registration #2	2011-09-05	20.693 mi
Registration #3	2012-08-30	26.076 mi
Registration #4	2013-08-29	30.395 mi
Registration #5	2014-09-20	35.529 mi
Registration #6	2015-09-28	42.168 mi
Registration #7	2015-09-28	42.168 mi
Registration #8	2016-09-24	48.690 mi
Registration #9	2017-09-19	52.308 mi
Registration #10	2018-09-20	55.000 mi
Registration #11	2018-09-20	55.000 mi
Registration #12	2018-09-20	55.000 mi
Registration #13	2018-09-20	55.000 mi
Registration #14	2018-09-20	55.000 mi
Registration #15	2018-09-20	55.000 mi
Registration #16	2018-09-20	55.000 mi
Registration #17	2018-09-20	55.000 mi
Registration #18	2018-09-20	55.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	131943
---------------	--------