




report date: 2024-03-28

General information

Make	KIA
Model	SOUL CRDI TEMPEST
Colour	Silver
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	11.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.9 mpg
CO2 emission	155 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-08-28
Pictures	2
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-07-28
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	34
Total items failed	27

MOT #19	2023-07-29 15:23
MOT test number	320506829362
Result	✓ Passed
Next expiry date	2024-07-28

MOT #18	2022-10-31 12:35
MOT test number	662962072303
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing inner wall (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing inner wall (5.2.3 (d) (ii))

MOT #17	2022-10-31 12:07
MOT test number	131951211972
Result	✗ Failed
Fail	Road wheel fixing missing x4 (5.2.1 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing inner wall (5.2.3 (d) (ii))
Pass with rectification	Electronic stability control warning lamp indicates a fault removed with machine and remained off for duration of the test (7.12 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing inner wall (5.2.3 (d) (ii))



MOT #16	2021-08-26 12:37
MOT test number	389669757189
Result	✓ Passed

MOT #15	2021-05-26 09:20
MOT test number	343871765903
Result	✓ Passed

- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive AXLE (5.3.6 (a) (i))
- Advice** UNDERTRAYS FITTED NOT ALLOWING FULL INSPECTION
- Advice** Front Macpherson strut corroded but not seriously weakened BOTH (5.3.3 (b) (i))
- Advice** Offside Rear CHILD SEAT FITTED NOT ALLOWING FULL INSPECTION
- Advice** Front Inner Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14**

2021-05-24 10:05

MOT test number

191450244594

Result**✗ Failed****Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive AXLE (5.3.6 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** UNDERTRAYS FITTED NOT ALLOWING FULL INSPECTION**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Offside Brake pipe excessively corroded FRONT TO REAR AT FLEXI HOSE (1.1.11 (c))**Fail** Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear CHILD SEAT FITTED NOT ALLOWING FULL INSPECTION**Advice** Front Inner Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Front Macpherson strut corroded but not seriously weakened BOTH (5.3.3 (b) (i))**Fail** Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13** 2020-05-28 13:44**MOT test number** 481020531493**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2020-05-19 09:13**MOT test number** 357677841187**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2019-05-01 10:00**MOT test number** 307032296437**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #10**

2018-07-31 15:46

MOT test number

245222838495

Result

✓ Passed

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9

2018-07-30 12:00

MOT test number

185450196074

Result

✗ Failed

Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Tyre worn close to legal limit/worn on edge all 4 (5.2.3 (e))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Nearside Headlamp aim too high (4.1.2 (a))

Advice Brake disc worn, but not excessively both front (1.1.14 (a) (i))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8** 2017-08-03 08:37**MOT test number** 408298070725**Result** ✓ Passed**MOT #7** 2017-08-02 15:24**MOT test number** 973712173608**Result** ✗ Failed**Fail** Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #6** 2016-08-10 16:07**MOT test number** 495396127765**Result** ✓ Passed**MOT #5** 2016-08-10 16:07**MOT test number** 269510965148**Result** ✗ Failed**Pass with rectification** Nearside Side repeater incorrect colour (1.4.A.2f)**Pass with rectification** Offside Side repeater incorrect colour (1.4.A.2f)**MOT #4** 2015-09-07 14:13**MOT test number** 999931215545**Result** ✓ Passed**MOT #3** 2014-09-19 08:43**MOT test number** 326552764255**Result** ✓ Passed



MOT #2	2014-04-15 09:49
MOT test number	346965904170
Result	✓ Passed

MOT #1	2014-03-05 11:13
MOT test number	767324664041
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
28 July 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	28 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-03-14
Last registration	2023-07-29
Complete history	See info



Registration #1	2011-03-14	11 mi
Registration #2	2014-03-05	30.566 mi
Registration #3	2014-04-15	30.793 mi
Registration #4	2014-09-19	30.884 mi
Registration #5	2015-09-07	37.496 mi
Registration #6	2016-08-10	42.950 mi
Registration #7	2016-08-10	42.950 mi
Registration #8	2017-08-02	59.569 mi
Registration #9	2017-08-03	59.569 mi
Registration #10	2018-07-30	75.361 mi
Registration #11	2018-07-31	75.362 mi
Registration #12	2019-06-29	91.277 mi
Registration #13	2019-06-29	91.277 mi
Registration #14	2019-06-29	91.277 mi
Registration #15	2019-06-29	91.277 mi
Registration #16	2019-06-29	91.277 mi
Registration #17	2019-06-29	91.277 mi
Registration #18	2019-06-29	91.277 mi
Registration #19	2019-06-29	91.277 mi
Registration #20	2019-06-29	91.277 mi
Registration #21	2019-06-29	91.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1360 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBBH537098