





report date: 2024-03-29

General information

Make	MINI
Model	PACEMAN COOPER S
Colour	Black
Year of manufacture	2015
Top speed	141 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2022-07-24


Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-03
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	10
Total items failed	7

MOT #8	2023-10-02 10:15
MOT test number	277801172634
Result	✓ Passed
Next expiry date	2024-10-03

MOT #7	2022-10-04 11:11
MOT test number	850383539967
Result	✓ Passed

MOT #6	2022-10-03 16:26
MOT test number	136710012537
Result	× Failed
Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i))	

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #5 2022-10-03 13:48

MOT test number 997728824657

Result X Failed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i))

Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #4 2021-08-31 13:53

MOT test number 103208629058

Result ✓ Passed

MOT #3 2020-07-06 13:48

MOT test number 339260183591

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2019-05-07 09:29

MOT test number 153917757508

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2018-05-23 07:49

MOT test number 693209530812

Result ✓ Passed

Advice Offside Front Upper Tyre worn close to legal limit/worn on edge reading 2.5mm (5.2.3 (e))

Advice Nearside Front Upper Macpherson strut mounting damaged but not seriously weakened top mount rubber spliting (5.3.3 (b) (i))

Advice Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Macpherson strut mounting damaged but not seriously weakened top mount rubber spliting (5.3.3 (b) (i))

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	3 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

\sim			
Own	or h	ist <i>i</i>	าrv
	וו וט	IJU	יוע

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		?

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	NE NE	
Plate since	1111	mm
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-29
Last registration	2023-10-02
Complete history	See info



Registration #1	2015-05-29	11 mi
Registration #2	2018-05-23	26.804 mi
Registration #3	2019-05-07	35.989 mi
Registration #4	2020-07-06	41.763 mi
Registration #5	2021-08-31	44.552 mi
Registration #6		77,777 44
Registration #6 Registration #7		11.777 es
-		11.777 es
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 12/1

Number of axles 2

Engine number A072J893