





General information

Make	KIA
Model	CEED CRDI 2
Colour	Silver
Year of manufacture	2011
Top speed	117 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	255 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	С







Internet history

Entry 1	
Date	2021-02-01
Pictures	10
Listing price	<u>View report</u>









source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-11
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	24
Total items failed	1

MOT #14		2024-01-08 10:46
MOT test	MOT test number 55845975353	
Result		✓ Passed
Next expiry date 2025-01-11		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)) (ii))
Advice	dvice Rear Brake hose has slight corrosion to ferrule n/s and o/s (1.1.12 (f) (i))	
Advice (a) (i))		
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear Subframe corroded	

MOT #13		2024-01-08 10:46	
MOT test number 95249168230		952491682309	
Result		🗙 Failed	
Advice	Rear Brake hose has slight corrosion to ferrule n/s and o/s (1.1.12 (f) (i))		
Advice	Rear Subframe corroded		
Advice	Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice (a) (i))	Rear Suspension arm pin or bush worn but not resulting in excessive mover	nent n/s and o/s (5.3.4	
Pass wi	th rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))		
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		





MOT #12		2023-01-12 17:30
MOT test	number	568913673893
Result		✓ Passed
Advice	Rear Brake hose has slight corrosion to ferrule Both (1.1.12 (f) (i))	
Advice	Rear subframe corroded	
Advice	Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	
MOT #11		2023-01-04 09:37

		2023-01-04 09:37
MOT test	number	885210610548
Result		🗙 Failed
MAJOR	Front Windscreen washer not working (3.5 (a))	
Advice	Rear subframe corroded	
Advice	Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	
MAJOR	Rear fog lamp not working (4.5.1 (a) (ii))	
Advice	Rear Brake hose has slight corrosion to ferrule Both (1.1.12 (f) (i))	

MOT #10	2022-01-04 11:46
MOT test number	863988310505
Result	✓ Passed
AdviceRear subframe surface corrosionAdviceFront Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	

МОТ #9	2021-01-05 16:50
MOT test number	745429122626
Result	✓ Passed





MOT #8	2020-09-01 12:44
MOT test number	440535700552
Result	✓ Passed
NOT #7	2010 11 07 11.21
MOT #7	2019-11-07 11:31
MOT test number	963082203975
Result	✓ Passed
Advice Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #6	2018-11-14 13:23
MOT test number	211386443624
Result	✓ Passed
Advice Both front tyres low on tread	
MOT #5	2017-11-17 15:28
MOT test number	966317123626

Result

MOT #4		2017-07-12 09:05
MOT test	number	143628523491
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2016-07-13 08:56
MOT test number	530255549477
Result	✓ Passed

✓ Passed





MOT #2	2015-06-17 09:19
MOT test number	287498965185
Result	✓ Passed
MOT #1	2015-01-22 09:14
MOT test number	956972925046
Result	



Tax & MOT check

Taxed Taxed 1 August 2024	Expires: 11 January 2025	✓ МОТ
Tax status		Valid until 1 August
Days left		93
MOT expiry date		11 January 2025
Full MOT history		See MOT history
Tax calculation		

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	
Category	 AMPL
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-30
Last registration	2024-01-08
Complete history	See info



Registration #1	2011-09-30	22 mi
Registration #2	2015-01-22	12.469 mi
Registration #3	2015-06-17	13.781 mi
Registration #4	2016-07-13	18.200 mi
Registration #5	2017-07-12	21.991 mi
Registration #6	2017-11-17	23.088 mi
Registration #7	2018-11-14	32.507 mi
Registration #8	2019-11-07	41.669 mi
	2019 11 07	
Registration #9		11.777 mi
-		11.227 est
Registration #9		01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11		00.000 est 0.000 est 00.000 est 0.000 est 00.000 est
Registration #9 Registration #10 Registration #11 Registration #12		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10 Registration #11 Registration #12 Registration #13		00.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1790 mm
Height	1480 mm
Length	4260 mm
Wheel base	2650 mm
Kerb weight	1468 kg
Max. allowed weight	1820 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number Carcheck.co.uk	D4FBBZ342052 page 13/13